

狮山博世力士乐DKC01.3-200-7-FW伺服驱动器F226故障修理过程分享

产品名称	狮山博世力士乐DKC01.3-200-7-FW伺服驱动器F226故障修理过程分享
公司名称	佛山市捷德宝科技有限公司
价格	180.00/台
规格参数	用途:伺服工控系统 品牌:力士乐Rexroth 系列:DKC
公司地址	佛山市南海区狮山镇小塘长安路玉兰楼一楼1、2号铺(住所申报)
联系电话	13169959558 13169959558

产品详情

狮山博世力士乐DKC01.3-200-7-FW伺服驱动器F226故障修理过程分享

狮山力士乐伺服驱动器维修：前两天狮山一家做生物医学的工厂联系我们，他们车间的伺服驱动器出现了问题，刚开始启动后还好，但运行一段时间后显示报警代码并且有噪音，现在已经停机了，主要显示F226Undervoltage Error，一段英文字母、车间的工人也没整明白啥情况。

力士乐伺服驱动器灯闪维修：故障说明：

因为距离不远，客户亲自拿过来，拿到设备之后工程师时间查明了故障说明情况，F226Undervoltage Error欠电压错误。

Description:故障说明：

The level of the DC bus voltage will be monitored by the drive controller. If

the DC bus voltage falls below a minimal threshold, the drive independently shuts down according to the set error reaction.直流母线电压水平将由驱动器控制器监控。如果直流母线电压低于小阈值，驱动器根据设置的错误反应独立关闭。

Cause:原因：

1. The power source has been interrupted without first switching off the drive enable (RF).电源已中断，但未首先关闭驱动器启用（RF）。

2. Disturbance in the power supply电源干扰

Remedy:解决措施：

1 Check the logic regarding the activation of the drive within the connected control.检查所连接控制装置内驱动器激活的逻辑。

2 Check the power supply. The error can be cleared by removing the control enable signal.检查电源。可以通过删除控制启用信号来清除错误。