

				m)	能过颗粒 直径(mm)	压力(kbf/ cm ²)	消耗量(m ³ /min)	铝合金	不锈钢	铸造铁	增强聚 丙烯
qby-10	0-0.8	0-60	6	5	1	7	0.3				
qby-15	0-1	0-60	6	5	1	7	0.3				
qby-25	0-2.4	0-60	6	7	2.5	7	0.6				
qby-40	0-8	0-60	6	7	4.5	7	0.6				
qby-50	0-12	0-60	6	7	8	7	0.9				/
qby-65	0-16	0-60	6	7	8	7	0.9				/
qby-80	0-24	0-60	6	7	10	7	1.5				/
qby-100	0-30	0-60	6	7	10	7	1.5				/

注: - 有 / - 无