

# 韶关力士乐伺服驱动器显示E250故障维修|力士乐驱动器维修

产品名称	韶关力士乐伺服驱动器显示E250故障维修 力士乐驱动器维修
公司名称	佛山市捷德宝科技有限公司
价格	300.00/台
规格参数	用途:力士乐驱动器维修 品牌:REXROTH伺服器维修 系列:伺服驱动器维修
公司地址	佛山市南海区狮山镇小塘长安路玉兰楼一楼1、2号铺(住所申报)
联系电话	13169959558 13169959558

## 产品详情

韶关力士乐伺服驱动器显示E250故障维修|汕尾力士乐驱动故障维修

力士乐驱动器故障代码E250：Heatsink Overtemperature Warning散热器过热警告。一般在伺服驱动器维修过程中，不同的现象，产生的故障大有区别，驱动器是用来控制伺服电机的一种控制器，其作用类似于变频器作用于普通交流马达，属于伺服系统的一部分，主要应用于高精度的定位系统。

韶关力士乐伺服放大器维修师傅：

E250 Heatsink Overtemperature Warning

散热器过热警告

Description:说明：

The temperature of the heatsink in the drive controller has reached the maximum allowable temperature. Within a time frame of 30 seconds, the drive follows the command value input. Consequently, there exists the possibility to shut down the motor with the control so that it remains true to

the process. (For example close the operation, leave the collision area,  
etc.) After 30 seconds, the parameter "Best Possible Deceleration, P-0-  
0119" set reaction appears during operation.

驱动器控制器中的散热器温度已达到高允许温度。在30秒内驱动器遵循命令值输入。因此，存在使用控制装置关闭电机的可能性，使其保持正确这一过程。（例如，关闭操作，离开碰撞区域，30秒后，参数“佳可能减速，P-0-0119”设置反应在操作过程中出现。