

# 代理德国原装 魏德米勒 Weidmuller 全系列产品

产品名称	代理德国原装 魏德米勒 Weidmuller 全系列产品
公司名称	杭州唐吉自动化有限公司
价格	面议
规格参数	品牌:魏德米勒Weidm ü ller 型号:SAK系列W系列Z系列
公司地址	中国 浙江 杭州市西湖区 余杭塘路173-1号 (翠苑北面, 电子市场、文化商城东面)
联系电话	86 0571 28815557/88094678

## 产品详情

杭州唐吉自动化有限公司专业经销德国魏德米勒weidm ü ller接线端子 接线盒 继电器 电源 pcb产品 工具 重载接插件 总线接口 电子产品, 备有大量库存, 现以优惠价提供给各地客户。

唐吉公司秉承友好开放的态度, 欢迎各位朋友、同行前来交流、咨询、合作。

[www.weidmuller.com.cn](http://www.weidmuller.com.cn)

+8621-2219 5008

杭州办+86571-8515 4262, +86571-8515 4784

魏德米勒weidm ü ller接线端子型号:

tst 2/m6seri a 3.5 d 128bfsc m4x9tbm m 4sak 4 orap sak4-10 dbap sak4-10 orask 1/en/kohue orap  
ask1 orsakt 1/35/ltsakt 1/35/lt stb25/4sakt 1/35/lt stbsakt 1/35/lt stb/pasakt 1/35/qt1sakt 1/35/qt1 pasakt 1/35/du1sakt  
1/35/du1 pasakt 2/35/lt/stbsakt 2/35/lt 4stbsak 2.5/tc alsak 2.5/tc al blsak 2.5/tc chsak 2.5 sw 1x1/krqsak 2.5 sw 1x1akz  
2.5 k sw u/v 1x1sak 6 krgsak 10 krgsak 10sak 10 krg/blsak 10 blsb 12ql 2 sakb10ql 3 sakb10ql 4 sakb10ts 15x5/ll  
2m/st/znts 15x5/ll 1m/st/znap sak4-10 rtap sak4-10 iap sak4-10 krgap sak4-10 krsap sak4-10ap sak4-10 krg/blap  
sak4-10 bltw akz4 krg/dbtw akz4 krsts 32x15 2m/st/znts 32x15 1m/st/znsb 17ql 2 sak35ql 3 sak35ql 4 sak35vl 2  
sak35sakt 1/35/qt2sakh 6 ep/swsakh 6sakh 10 ep/swsakh 10 krgsak 4 ep/swsak 4 krgsak 4sak 4 krg blsak 4 blbfsc m3x22  
pa/rtbfsc m4x32 pa/rtsaki 4/20 30r poti cuntstg mtgstb 7.5/d6/4/m4 zb/sakbtw sak4-10 ep/swtw sak4-10 krgtw 4  
sak4-10tw sak4-10 krg/bltw 4 sak4-10 blstb 6/d3.9/2.3/m2.5 zbql 2 sak4ql 3 sak4ql 4 sak4ql 2 sakh10ql 3 sakh10ql 4  
sakh10ap sakh6-10 ep/swap sakh6-10 krgap sakh6/10 krsql 2 sak10-sak35tsch 2/sakt2 orstb 28.5 ih/sw sak2.5qb  
25/6.5/11.5 sakrsaka 10ap saka krgks 2 o.d2d2 ks2 tpts 15x5 2m/al/bksakb 10q 5 sak2.5stb 13.5/d6/4/m4 saka10sb 14ql  
2 saka10ql 3 saka10ql 4 saka10vl 2 sak16/sakavl 2 sak6/10/sakbq 5 akz4ss m4 d 128-a 4sakb 10  
qval 1p 14/2 d01 rs saks4p 14/4 d01 br saks4sak 70/35stb 16/d7/4/m4 sak35ks 4 o.d4d4 ks4 tpsk 6 o.d6d6 ks6 tpsk 10  
o.d10d10 ks10 tpsake 35ap sakb/c/t krgap sakb/c/t bestb 17/d6/4/m4 sakc10sakg 70 ii/gwap sakd2.5nap sakd2.5n bltw

sakg28 hp/dbr/2sst 3 2mql 2 sak2.5ql 3 sak2.5ql 4 sak2.5cpsb m6cpsb m8cpsb m10cpsb m12akz 4 sf se 6.3/2.8d2 ks2d4 ks4saks 4 usaap aka2.5dk 4/35 2d get.sch.tstw 6/m6ep al1 hp/dbr/1ss m3 d 128-a 3ep al1  
hp/ff/ge/1tw sakg28 hp/ff/ge/2sta 2.5/2sta 2.5/3sta 2.5/5sta 2.5/8tw akz4 hp/dbr/0.5ql 3 sak70stb 14/d5/2.3/m3  
sak2.5sak 4 cun/ep/swsak 4 cun krgsak 4 cunsak 10 cun krgts 32x15 2m/al/bksst 3 2m msstb 14/d6/4/m3 sak10sakg 28  
isakg 28 iisakg 32 iisakg 40 iisakg 46 iisakg 54 iisakg 28 iisakr/35sagr/35 blsaks 1/35 g20 gb 24vdcakz 2.5 o.zatw sakg46  
hp/dbr/2ap sak4-10 krg/dbtstw 5/m5saks 4/35 usaad 3 sak10ad 4 sak10ad 4 sak35tw sakg46 hp/ff/ge/2ps 2.3 rtep 1  
sakg32/35 hp/dbrep 1 sakg32/35 hp/ff/geep 2 sakg46/35 hp/dbrep 2 sakg46/35 hp/ff/geep 2/bw sakg46/35 hp/dbrep  
2/35 8wa1 822-7tx01sagr/35 2stbsagr/35 2stb blsakg 28 ii/gwsakg 32 ii/gwsakg 40 ii/gwsakg 46 ii/gwsakg 54  
ii/gwsakrd/35sak 2.5/tc cosak 2.5/tc cusak 2.5/tc feek 16/35tsch 6 dki s4ql 6 sak10saks 1/g25saks 1/g20ap saks1 3  
krq/dbap saks1 3 krgql 2 saks1ql 3 saks1ql 4 saks1tw sakd2.5ntw sakd2.5n blsak 6n krgsak 6nsak 6n blql 2 sakg32 70ql  
2 sakg40ql 2 sak6nql 3 sak6nql 4 sak6nvl 2 sak6n/saktsakt 1/du1ad 4 sak6nvl 2 sak4tw sak4-10 hp/dbr/0.5sakt e/35 2ld  
60vacstakt e/35 2gl 115vacstakt e/35 2gl 230vacstakt e/35 2ld 120vacstaks 1/35 g25 gl 230vacewk 2bfsc m3x7 stv1/5saks  
1/g25 cunsaks 1/35 g20 gl 230vacsn bk 2-12bkst 4bkst 6d6 k6d10 ks10sak 10 stanbklw 4/vsbklw 6/vsbklw 12/vsbkst  
2bkst 3bkst 12ep 1 sakg28/32 hp/dbrep 1 sakg28/32 hp/ff/geep 2 sakg46/32 hp/dbrep 2 sakg46/32 hp/ff/geeqb 2  
sakt1qb 3 sakt1ewk 1saks 2ds 14 sak4ds 12.5 sak10ds 12.5 sak6nql 2 saks2ql 3 saks2ql 4 saks2p 16/10 rt saks2p 16/16 gr  
saks2p 16/20 bl saks2dk 4/35 ld gr 24vdcdk 4/32 ld rot 24vdcdk 4/35 ld rot 24vdcdk 4/35 ld gr 24vdcadlsaks 3  
z/6.3x26ake 4 msap sakr krgap sakr beap sakr blql 2 sakg40/35qs 2/6.5/2.3 sak4sak 6/en rtsak 6/ensak 6/en blsak  
6/10/en/bezsake 70/32sls 2/2 6.3saks 1/35 g20 ld 48vacstakt 2.5nsakd 2.5n blstb 8.5/d4/2.3/m2.5 akzql 2 sakd2.5nql 3  
sakd2.5nql 4 sakd2.5nmf 1/6 4x6.3mf 1/8 4x6.3dk 4ss/35 ff 4x6.3/2.8sv 2ts 15x5/ll 2m/al/bksak 2.5/ensak 2.5/en blql 5  
sak2.5ql 5 sak4ql 5 sak6nql 6 sak6nql 15 sak6nask 1/en ld 15k 24vdcask 1/en ld 1d 24vacask 1/en ld 27k 48vdcask 1/en  
ld 1d 48vacask 1/en ld 56k 115vdcask 1/en ld 1d 115vacask 1/en ld 120k 230vdcask 1/en ld 1d 230vacstaks 1/35 g20 ld  
24vdcask 1/en ld 33k 60vdcst 35x15 2m/st/znts 35x15 1m/st/znts 35x15/ll 2m/st/znts 35x15/ll 1m/st/zntast 3 6.3sls 2/4  
6.3mk 2/12mk 2/12 sl/wamf 2/12 1x2.8/1.6mf 2/12 2x2.8sak 6n cun/krqsk 6n cuntw sakb-c-ttw sakb/c/t1mk 3/12mk  
3/12 blmkl 3/12 wamk 5/2 o.ded 2 mk5/2 pa/namk 4/16mkl 4/16 sestb 8.5/d4.5/2/m3 sakt4ap sakt4 krgql 2 sakg46sp  
90 lf 6.3vh 13.5/4.9/3.3 sak4saks 3 gz/6.3x32vh 12/4.9/3.3 sak6nkmvf li 6.3 ep/swkvmvf re 6.3 ep/swkvmvt li 2.4  
ep/swkvmvt re 2.4 ep/swzvs 2.3/4mkl 3/12 sesakt 4/lt o.stbsakt 4/lt stb2.3tw sak2.5-35/32 krghp 7 tsk31.5hp 8 adp 1ew  
35/scha/m3ewk 2/scha/m3/lssch 10x3x1000 ms/bksakb 10 cmk 1/3 sl/ramk 1/12 sl/ramkl 4/16 waad 4 wsd sakg40  
hp/dbrql 3 sakg40sakrd dls2ql 2 sakg54vh 20/8/5 sak35ast 1 6.3 dbast 1 6.3 krgast 1 6.3ap ast1 5 dbap ast1 5 krgap ast1  
5zb 35/m6x16vh 8/4.9/3.3 sak2.5bfsc m2.5x14 sakd2.5nvh 8.5/4/2.8 sakd2.5nvh 17/8/5 sak35bfsc m4x30stb 25 ih/geql  
2 rsf1 2/sak10zu16ql 3 rsf1 2ql 4 rsf1 2sakd 2.5/35sakd 2.5/35 blsakt 1/lt stb25/4sakt 1/ltsakt 1/qt1sak 2.5sak 2.5 blts  
35x15/2.3 2m/cu/bkrf1 1 krgap rsf1 krgap rsf3qs 2/12/4qs 2/10/4qs 2/8/4sak 16 krgsak 16sak 16 blap sak16 krgap sak16  
krsap sak16ap sak16 blstb 25 ih/gnstb 25 ih/vistb 25 ih/grstb 25 ih/swep 1/bw sakg28/32 hp/dbep 2/bw sakg46/32  
hp/dbans unad 3 sak35mk 3/2mk 3/2 blmk 3/3mk 3/4mk 3/4 b 1-4mk 3/5mk 3/6mk 3/6 blmk 3/7mk 3/8mk 3/8 blmk  
3/10mk 3/11mkl 3/2 wamkl 3/4 wamkl 3/6 wamkl 3/8 wamkl 3/10 wamkl 3/4 semkl 3/6 sebsk (m3x30) (red plastic)ql  
3/ss6ap sak2.5 krgap sak2.5 krsap sak2.5 rtap sak2.5ap sak2.5 krg blap sak2.5 blsak 2.5 krgsak 2.5 krssak 2.5/ap ggsak  
2.5sak 2.5 krg/blsak 2.5 bldksue nsch/eschnsch 1mesch 1 mstb 8.5/5/2.3/m3 sak2.5tw sak16 krgsk saks1/g25sk  
g20/saks1ad 4 wsd sakg32 hp/dbrsk e16/saks2ql 2/ss6dkis 4 be/bevh 19/5/3.5 sak4-16vh 17.5/5/3.5 sak6n-16ad 4  
sak4shstb 18/rsf1sakg 32 isakg 32 iisakg 40 isakg 40 iimk 7/18mk 7/18mk 7/18bfsc m3x25ts 32x15 2m/crnps 2.0  
orsakr ll 2stbakz 4 krgakz 4akz 4 blap akz4 krgap akz4 krsap akz4ap akz4 blgz 2.0agz 5.0agz 3.0afksc m5x8  
d9/sw2.5bfsc m5x8vh 5/4/2.8 akz4dk 4ss/35 ff 8x2.8tw sak2.5 hp/ff/ge/1ql 2 dliql 3 dliql 4 dlisaks 3 g/5x30 500vad 3  
sak4ad 3 sak6nad 3 sak16ad 3 sak2.5ast 3 6.3 krgap ast3 4 krgvh 24.5/8/5 sak35bfsc m4x35sakrd/35 dls2ps 4 f.stb 4vh  
13.6/7/4.2 saka10sh 1sakrd/35 o.dls2dqz 2 f.sakt4 m.brueckeaka 2.5aka 2.5 blvh 12.5/5/3.5 sak10-2.5adk 1/2.5ap rsf2  
krqtop 1.5f/32 b/1-32sak 2.5 cun/krqsk 2.5 cuntw sak2.5 krgtw sak2.5tw sak2.5 krg/bltw sak2.5 blkisc m3x20.5/10  
ek4vh 4.5/5/3.5 sak6n-16bfsc m2.5x18 pa/rtad 4 akz4sak 35 krgsak 35sak 35 blap sak35 krgap sak35/tw sak16ap sak35  
krg/blap sak35/tw sak16 bladk 1/1.5vh 13/5/3.5 sak 10tw sak35 ep/swtw sak35 krgtw sak35saks 1/32 g20 gl 230vacst  
1.2 v2a/bk ts15qvs 2 sakt1 2qvs 4 sakt1 2tw sakd2.5n hp/ff/0.5sak 4/10ap sak2.5l krgsaks 1/32 g25 gl 230vacvh 27/5/3.5  
sak10-35vh 21/5/3.5 sak16-35vh 16/5/3.5 sak10-35bfsc m3x35ts 20/cx10 2m/st/zntz 4zb 16 zksc 16/4vh 19/6/4.2  
sakt1tw akz2.5tw akz2.5 bltsch 1sak 2.5 lansf 1.6/33.5bb 1 akb 4dls 2 scmu sakrdsaks 4akb 4akb 4 blzb 4g swzb 4g  
gn/gezb 4g blsak 2.5/10ek 1ek 2sakc 10 stb/resakc 10 2stbakz 4 s wa 2x2.8akz 4 ss se 6.3/2.8ah 28 sakg28ah 32 sakg32ah  
40 sakg40ah 46 sakg46dkt 4/35 2stbql 2 saks4ql 3 saks4ql 4 saks4p 14/6 d01 gn saks4p 14/10 d01 rt saks4saks 3/35  
g/5x30 500vap sakt2 krgsakr cunqvs 3 sakt1 2ap akz1.5wql 2 akz1.5sakt 2/lt stbts 35x7.5 2m/al/bkds 9 sak2.5aft

apaftmbb 25/aftabb 25/aftast 5 sf 6.3 krgbs 25 o.ih sakt1akz 4l sl vs krgakz 4l sl vsbs 25 ih/sw sakt1bs 25 ih/gr sakt1bs 25 ih/bl sakt1bs 25 ih/rt sakt1bs 25 ih/gn sakt1bs 25 ih/ge sakt1bs 25 ih/vi sakt1q 2 akz4q 3 akz4q 4 akz4q 2 sak4q 3 sak4q 4 sak4q 2 sak2.5q 3 sak2.5q 4 sak2.5sak 10/enql 10 sakd2.5nql 10 sak2.5ql 10 sak4ql 10 sak6nql 10 saka10ql 10 sak35ql 10 sakh10ql 10 saks1ql 10 saks2ql 10 saks4ql 10 akz1.5ql 10 dlisk e14 saks4sak 16/ensak 35/enakz 1.5l vsakz 1.5sak 1.5 blap akz1.5ap akz1.5 blsac 4 2stb7sac 4 krgsak 70 krgsak 70 krg/blap 70 sak70 krgap 70 sak70 krsap sak70/35stb 30.5 ih/swstb 30.5 ih/grstb 30.5 ih/blstb 30.5 ih/rtstb 30.5 ih/gnstb 30.5 ih/gestb 30.5 ih/viql 10 rsf1 2bfsc m2.5x20.35 wpe2.5stb 25 ih/rtstb 25 ih/blqb 10 sakt1akz 4 st wa 1.6ad 3 sak70ql 2 sak70vh 30.5/11/5.5 sak70bfsc m5x45ss m5 d 128-a 5kisc m3x6 saks1akz 4 ll vstw akz4ap sb4.8ewk aka 2.5vh 23/6/4.2 saka10ssch 10x3x1000 cu/snsak 2.5 sl krgsak 2.5 sltw sakt2hp nt2.5hp nt2.5 blnt 2.5 10x3 blaftnt 6 10x3 bent 6 10x3 blhp nt6/10hp nt6/10 blsak 4 ss 6.3/krgfksk m6x12 d9/sw3tsch 2ek 4ek 10ek 35dk 4dk 4 blssch 15x6x1000 cu/snsak 4/35sak 4/35 dbsak 4/35 blsac 4/35 2stb7akz 1.5/10qvs 2/s sakt1 2stb 7/d4/2.3/m3 zb/sakckisc m3x15/6 sak2.5ap dk4ap dk4 blsaks 5 380acakz 4/10akz 4/10/bezp 18/20 d02 bl saks5p 18/25 d02 ge saks5p 18/35 d02 sw saks5p 18/50 d02 ws saks5akz 4 ss wa 2x2.8bfsc m4x20tsch 4 akz4dk 4qv/35dk 4qv/35 blak 95adk 1/2.5 ts 1.6adk 1/1.5 ts 1.6ak 4/10bb 3 ak4tsch 3 sakd2.5 nkisc m2.5x15/5.5 sakdq 2 sakd2.5nq 3 sakd2.5nq 4 sakd2.5nq 10 sakd2.5nq 5 sakd2.5nq 6 sakd2.5nq 7 sakd2.5nq 8 sakd2.5nq 2 akz1.5q 3 akz1.5q 4 akz1.5q 10 akz1.5q 10 akz4q 5 akz4q 6 akz4q 8 akz4q 10 sak2.5q 5 sak2.5q 6 sak2.5q 7 sak2.5q 8 sak2.5q 9 sak2.5q 10 sak4q 5 sak4q 6 sak4q 7 sak4q 8 sak4q 12 sak4q 20 sak4q 10 sak4 cunq 2 akz4ssq 3 akz4ssq 4 akz4ssq 10 akz4sstw sak2.5-10 hp/ff/ge/2mk 10/14sak 2.5 ts se 2.4/krgsaks 1/32 g20 ld 24vdcadk 1/2.5 ws 1x1ek 16ad 4 enad 4 sak6/10 enad 4 sak6n enad 4 sak4 enask 1ask 1/15ask 1/dmkisc m3x20 sak10 cu5kisc m3x15/6 sak2.5 cu5saks 1 g20 gb 48 dcstb 6/d3.7/2.3/m3 sakrake 4ap ask1ap ask1 blsak 2.5/35 krgsak 2.5/35 orsak 2.5/35 ap ggsak 2.5/35sak 2.5/35 krg/blsak 2.5/35 blsak 6/35 krgsak 6/35 pasak 6/35 krg/blsak 6/35 pa/blsak 16/35 krgsak 16/35 pasak 16/35 pa/blsak 35/35sak 35/35 blsb 4.8-4/4sb 4.8-4/6ew 15ts 35x7.5 2m/st/znts 35x7.5 1m/st/znew 35 gr 7032ew 35ew 35 wssaks 1/32 g20 gl 115vacakz 2.5 m.apstb 35 ih/swstb 35 ih/grstb 35 ih/blstb 35 ih/rtstb 35 ih/gnstb 35 ih/gestb 35 ih/vidk 4/35 ld gr 24vdcadk 4/35 ld gr 24vdcadk 4/35 ld 1d rot 24vacdk 4/35 1d get.sch.dk 4/35 2d get.sch. a1dk 4/35 2d get.sch. a1dk 4/35 2d get.sch. a2dk 4/35 1d 1k5 get.schkisc m2.5x11/4.5 akz1.5nt 2.5 10x3 krg/blnt 6 10x3 krg/blsak 4 s 6.3/2.8/krgsak 4 s 6.3/2.8ap dusa4/35so sh1dusa 4/35 zadusa 4/35ah 2/4 wsa2ql 3 sakg28ql 4 sakg28ql 3 sakg54ap sakh 4exql 4 sakg40sagr krgsaksagr blsagr 2stb krgsagr 2stbsagr 2stb blsagr slsagr 15sagr 15 2stbsakrd o.dls2sakrdmk 7/3mk 7/4mk 7/6mk 7/8mk 7/10mk 7/12mk 7/16mk 7/2mk 7/5mk 7/7mk 7/10mk 7/12fcs (saks 3 red)sk sw saks3 gzfuse tdp44 0.25a fnfuse tdp44 0.5a fnfuse tdp44 1a fnfuse tdp44 3a fnfuse tdp44 4a fnfuse tdp44 5a fnfuse tdp44 6a fnfuse tdp44 0.75a fnfuse tdp44 2.5a fnfuse tdp44 9a fnksz 4sakt 2/lt 4stbsakt 1/lt stb14/4ssch 10x3x1000 st/zndk 4/380 qap dk4/380 qast 4 sf 6.3/2.8 krgql 3 sakg32 70ql 4 sakg32 70tw adk1 hp/dbr/0.5ast 3 6.3/2.8 krgakz 1.5 sw 0.6sak 4/35 krgsak 4/35sak 4/35 krg/blsak 4/35 blsak 10/35 krgsak 10/35sak 10/35 krg/blsak 10/35 blql 3 sakg46ql 4 sakg46sakt 2/lt o.stbmew 1/32akz 4 cun/krgakz 4 sw 1x1vh 10/4/2.8 akz4vl 2 akz4/dk4ap st5 ppo/swap st5 pa/bead st5/e l=1mst 5 pa/bestl 5mk 10/3mk 10/4mk 10/5mk 10/6mk 10/8mk 10/10mk 10/12posc m3x20 pa/naech 1 aptw ss6-12ask 1/en/kohueq 2 sak6nq 3 sak6nq 4 sak6nq 10 sak6nq 5 sak6nq 6 sak6nq 7 sak6nq 8 sak6nq 12 sak6nq 2 sak10q 3 sak10q 4 sak10q 10 sak10q 5 sak10q 6 sak10q 2 sak16q 3 sak16q 4 sak16q 10 sak16q 5 sak16q 6 sak16q 7 sak16zbe 6ap sak4 krg m.fuast 3/35 6.3/2.8ast 4/35 sf 6.3/2.8ap sak2.5/35 dbap sak2.5/35 ast3 4ap sak2.5/35 blqb 2 wi ra8 isqb 3 wi ra8 isqb 4 wi ra8 isrv 8/56 v.ii 2.4/1x1tst 10 sakc10st 5/slavr 4/10/32 wa 1.6avr 4/10/32 se 2.4avr 4/10/32 se 2.4 blsagr llrv 8/8/ku tw 2.4/1x1rv 8/8/ku tt 2.4/2.4sak 4/en orsak 4/ensak 4/en blsak 4/10/en/bezdk 4/32 1d csa a2rv 8/8/ln tt 2.4/1sagr ts se 1.6ak 4/10/beznt 10 10x3 blql 2 sak10ql 3 sak10ql 4 sak10ql 10 sak10ql 2 sak16ql 3 sak16ql 4 sak16ql 10 sak16dq 2 1d ps2,3 agdq 2 ps2,3 ag m.brueckdq 2 ps2.3 o.batent 2.5/35 10x3 bent 2.5/35 10x3 krg/blnt 2.5/35 10x3 blnt 10/35 10x3 krg/blnt 10/35 10x3 blek 2.5ndk 4/32 ld rot 24vdc a2ask 1/enask 1/en bltw ast1/pa hp/dbr/0.5zb 4k swzb 4k ge/gnzb 4k blik 4 sw zb4ik 4 gg zb4ik 4 bl zb4adk 1f/1.5ap adk1sak 35/ik krgsak 35/iktw st5 pa/beast 1 6.3/2.8 krgast 1 6.3/2.8adk 1s/2.5adk 1f/2.5ast 5 sf 6.3/2.8 krgast 5 sf 6.3/2.8ast 3/35 6.3ast 4/35 sf 6.3sak 4 ss 6.3/2.8 krgsak 4 ss 6.3/2.8mf 1/6 2x6.3/2.8mf 1/8 2x6.3/2.8mf 1/6 4x6.3/2.8mf 1/8 4x6.3/2.8mf 1/12 4x6.3/2.8qb 2 wi ra6 isqb 3 wi ra6 isqb 4 wi ra6 isap top4sf-ffdk 4/32 1d csa a1ss 10 bz28 pa/swsak 2.5 tt se 2.4/krgadp 1/hp1 1madp 2/hp2 1madp 3/hp3 1mhp 1 adp1hp 2 adp2hp 3 adp3hp 4 adp3sak 2.5 st wa 1.6/krgakz 4 l/10/f.ps sl vsak 4/o.zant 16/35 15x6 blsakt 1/qt2sh 2sak 2.5/35 slewk 1 altdk 4/32 ld rot 24vdc a1mofu 35rsf 3 pats 35x15/2.3 2m/st/zns 8 bz28 pa/swss 6 bz25 krgss 12 bz32 pa/swnt 16/35 10x3 bent 16/35 10x3 blnt 16 15x6 bent 16 15x6 blsak 2.5/10/35aftnt 6/35 10x3 krg/blsaks 1/35/g25 dbsaks 1/35/g25saks 1/35/g20 dbsaks 1/35/g20saks 4/35 dbsaks 4/35saks 5/35 dbsaks 5/35wsa 2/fue/rhzb 35k sw m6x16zb 35k ge/gn m6x16zb 35k bl m6x16ik 35/zb35 ggik 35/zb35 blzb 16k swzb 16k ge/gnzb 16k blik 16/zb16 ggik 16/zb16 bldk 4/32 gl 330k 230vacakz 4/exsak 2.5/35 sw 1x1ts

15x5 2m/st/znts 15x5 1m/st/zntsk 35x15 2m pvc/grts 32x15// 2m/st/znts 32x15// 1m/st/znts 35x7.5// 2m/st/znts 35x7.5// 1m/st/znts 35x7.5// 6 2m/st/znsak 4 spring loadedsagr ls 2stbad 4 sak16qb 25/6.2 is swqb 25/6.2 is rtqb 25/6.2 is bldk 4/32 2d csa a2dk 4/800vsakl 4/32 30r potirv 16/9gz 1.0a/fzbe 6k swzbe 6k ge/gnzbe 6k blqb 75/6.2/9/wiispf qb75 swispf qb75 rtisfp qb75 bldk 4/35dk 4/35 blstl 5/brvl 2 rsf 1 2wsa 2/fuesak 4/10/35sakt 1/l 1stbah 2/3 wsa2ssp 3 sakt1saks 6/gz 500acap dsk1.5ek 16/35/2zb bkqb 75/6.2/15ek 95/35/1zb bkek 95/35/2zb bkdsk 1.5/10/35ta 1dk 4 sw 1x1dk 4/35 1d a2dk 4/35 1d a1dk 4/35 1d a1dk 4/35 1d 24vdc csa a1dk 4/35 1d 24vdc csa a2sak 2.5 ls krgrv 8/20 0.8x2.4/0.8x2.4dk 4/32 1d csa get.sch.ta 2 sf/3.9/feap ta2qb 58/8/9/wiqb 58/8/15isfp qb58 swispf qb58 rtisfp qb58 bldls 2 sakrd drbrdls 2 sakrd /-sakt 1/du2sak 95 krgsak 35n krgsak 35nap sak95 krgap sak95 krg/blvh 35/11/5.5 sak95ql 2 sakg28kohue ask1sak 35n/iksak 35n/iknsch 2m o.bzsh 3zb 4/6zb 16/6ql 2 sak35nql 3 sak35nql 4 sak35nql 10 sak35nzb 4/6k ge/gnzb 4/6k blsak 2.5/35 lldk 4/32 gl 100k 115vaczb 16/6k ge/gnssch 6x6x1000 ms/bkssch 6x6x1000 cu/snsaks 7/g20ad 4 sak35nsak 35/35/ikdkit 4 bl/ggdki 4 bl/ggdki 4dk 4q/32dk 4q/32 bldk 4q/35 dbdk 4q/35 cundk 4q/35dk 4q/35 bldk 4qv/32dk 4qv/32 bldsk 1.5/1/35sakt e/32 2gl 230vactw saks2 hp/dbr/2tw ss6 hm/gr/2sak 35n/35 krgsak 35n/35sak 35n/35/ik krgsak 35n/35/iksak 35n/35/ik krg/blhp dki 4/s4/t4dk 4/32 2d csa get.sch.mk 6/6mk 6/4mk 6/3mk 6/2rsf 2eks 12/4eks 5waybk 2 crnbk 2 l&nbk 3 crnbk 3 l.n.e.bk 4 crnbk 6 crnbk 12 crnbklw 3klw 4bkst 4bkst 12dls 2 sakrd -/kisc m5x50/26 sak95sak 4 s/35 6.3/2.8 dbsak 4 s/35 6.3/2.8sak 4 ss/35 6.3/2.8 dbsak 4 ss/35 6.3/2.8dk 4s sf 6.3/2.8ap dk4q dbap dk4ssakl 4/32 10k potiad 250hp ek132/2 ad250ap dkit4klbue sh1klbue sh1sakg 70/35 ii/gwfm 5/ts35fm 6/ts35sakg 32/35 isakg 32/35 iisakg 32/35 iisakg 32/35 ii/gwsakg 40/35 isakg 40/35 iisakg 40/35 iisakg 40/35 ii/gwsakg 46/35 iisakg 46/35 ii/gwsakg 54/35 iisakg 54/35 ii/gwsh 2 sfksc m6x8 d9/sw3dk 4/32 2d csa get.sch.dk 4v/35sakl 4/32 500r potidkis 4 be/ggmofu 35/lo/1 swmofu 35/lo/1dk 4/32 1d gr 24vdc a2sakl 4/32 5k potisakl 4/32 10r potiss 6/35 bz25 krgad 4 sak35n enq 5 akz1.5ek 16/35/1zb bkek 2.5/35ek 4/35ek 6/35ek 10/35ek 35/35sak 95/35 krgsak 95/35 krg/bldk 4/35 gl 330k 230vacdk 4/32 2d a1dsk 1.5/1ast 1/35 6.3 dbast 1/35 6.3ast 5/35 sf 6.3/2.8 dbast 5/35 sf 6.3/2.8saks 3/35 (red cap)saks 3/35 gz/6.3x32dkt 4dk 4/32 1d 1k5dk 4s/35 sf 6.3/2.8dkt 4dkt 4/35ap dkt4 pafm 4/ts35ewk 1 pps/swakz 2.5 k sf s/s 2.8akz 2.5 gs 2sti4.5akz 2.5akz 2.5 blap akz2.5kap akz2.5ap akz2.5 blbb 4/akz2.5sakt e/32 2ld 60vacast 1/35 6.3/2.8 dbast 1/35 6.3/2.8wtr 4 sl rtwpe 2.5wpe 2.5 wswpe 4wpe 6wpe 10wpe 16wpe 35wnt 2.5 10x3 bewnt 2.5 10x3wnt 4 10x3 bewnt 4 10x3wnt 6 10x3 bewnt 6 10x3wnt 10 10x3 bewnt 10 10x3wsi 6wsi 6 swwsi 6 orwsi 6 blwtr 2.5wtr 2.5 swwtr 2.5 gewtr 2.5 gnwtr 2.5 rtwtr 2.5 grwtr 2.5 orwtr 2.5 blwtr 2.5 wswtr 2.5stb 2.3wtr 2.5 stb2.3 swwtr 2.5 stb2.3 gewtr 2.5 stb2.3 gnwtr 2.5 stb2.3 rtwtr 2.5 stb2.3 grwtr 2.5 stb2.3 orwtr 2.5 stb2.3 blwsi 6/ld 10-36v dc/acwnt 2.5 6x6wsi 6/o.tnhewsi 6/ld 30-70v dc/actnhe wsi6 10-36v dc/acwsi 6/ld 60-150v dc/acwsi 6/ld 250acwpe 35/ikscwtr 2.5/o.tnhe stb2.3wtr 2.5/d/o.tnhewtr 2.5 stb2.0wtr 2.5/o.tnhe stb2.0wtr 2.5/d stb2.3wtr 2.5/d- stb2.3wtr 2.5/d/drbr stb2.3wtr 2.5/dwtr 2.5/d-wtr 2.5/d/drbrwtr 2.5 lwtr 2.5 llwsi 6/2 gz/def63wsi 6/2/ld 10-36v dc/acwsi 6/2/ld 30-70v dc/acwsi 6/2/ld 60-150vdc/acwsi 6/2/ld 250acwtr 2.5 d 2stb 7.5/2.3wtr 2.5 d 2stb 7.5/2.3wdt 1.5/2 be/pa66/gewdt 1.5/3 be/pa66/gewdt 1.5/1 db/gewdt 1.5/2 db/gewdt 1.5/3 db/gewdt 1.5/3 bl/hbwpe 2.5nwpe 2.5/1.5/zrwpe 1.5/zzwtl 6/1wtl 6/1/32wtl 6/1/stbwtl 6/1/stb grwtl 6/1/stb rtwtl 6/1/stb/32wtd 6/1wtd 6/1 grwtd 6/1/32wtl 6/2wtl 6/2/32wtq 6/1wtq 6/1/stbwsi 6/2 o.tnhewtl 6/3/stbwtl 6/3 brwtl 6/3wnt 16n 10x3wpe 16nwpe 120/150wdu 2.5wdu 2.5 swwdu 2.5 gewdu 2.5 rtwdu 2.5 wap/ggwdu 2.5 orwdu 2.5 blwdu 2.5 gnwdu 4wdu 4 swwdu 4 gewdu 4 rtwdu 4 gn wap gewdu 4 gnwdu 4 blwdu 4 ge/swwdu 6wdu 6 swwdu 6 rtwdu 6 wap/ggwdu 6 orwdu 6 blwdu 10wdu 10 swwdu 10 grwdu 10 rtwdu 10 gn wap gewdu 10 orwdu 10 blwdu 16wdu 16 gn wap gewdu 16 blwdu 35wdu 35 swwdu 35 blwdu 35/ikwdu 35/ik blwdu 2.5/10 bezwdu 2.5/10 bez/newdu 4/10/bezwdu 4/10wdu 4 sawdu 2.5 ts se 2.4wdk 2.5wdk 2.5 orwdk 2.5 blwdk 2.5 fwdk 2.5 f blwdk 2.5 ffwdu 2.5 f 2x2.8wdu 2.5 ff 2x2.8wdu 2.5 ws 1x1wdu 2.5 slwdu 2.5 llwdk 2.5vwdk 2.5v gewdk 2.5v orwdk 2.5v blwdk 2.5 fvwdk 2.5 ffwdk 2.5 dwdk 2.5/dwdk 2.5 1d a.2wdk 2.5 1d a.1wdk 2.5 2dwdk 2.5 1d rot 1r 24vdcwdu 2.5nwdu 2.5n gn wap gewdu 2.5n orwdu 2.5n blwdu 2.5n gewdk 2.5 st se 2.4wdu 2.5/tc typ kwdu 2.5/tc typ twdu 2.5/tc typ jwdu 2.5/tc typ srwdu 120/150wdu 120/150 hgwd 120/150 blwdu 70/95wdu 70/95 hgwd 70/95 blwdu 2.5/1.5/zrwdu 2.5/1.5/zr blwdu 2.5 cunwdu 4 cunwdu 6 cunwdu 16 cunwdu 35 cunwdk 2.5/10wdu 120/150/5wdu 70/95/3wdul 4/10wdul 4/100wdul 4/500wdul 4/1kwdul 4/5kwdul 4/10kwdul 4/50kwdul 4/500kwdul 6 trwff 35wff 35 blwff 70wff 70 blwff 120wff 120 blwff 185wff 185 m12 m16wff 185 blwff 300wff 300 blwdu 35/zawdu 35/za blwdu 16/zawdu 16/za blwdu 35/ik/zawdk 2.5/800vwff 35/ahwff 70/ahwff 120/ahwff 185/ahwff 300/ahwff 2.5/nt/l/pewdl 2.5/tr/du/pewdl 2.5/tr-duwdl 2.5/n/l/pewdl 2.5/n/lwdl 2.5/nwdl 2.5/l/l/pewdl 2.5/l/lwdl 2.5/s/nt/l/pewdl 2.5/s/n/l/pewdl 2.5/s/n/lwdl 2.5/s/nwdl 2.5/s/l/l/pewdl 2.5/s/l/lwdl 2.5/s/lwdu 1.5/zzwdu 1.5/zz blwff 35/32wff 70/32wff 120/32wff 185/32wff 300/32wdu 70/95/5/nwdu 120/150/5 nwdu 2.5/ap/tc typ kwdu 2.5/ap/tc bl typ kwdu 2.5/ap/tc twdu 2.5/ap/tc bl typ jwdu 2.5/tc typ ewdu 2.5/tc typ bwma 4/5wma 4/4wdl 2.5/2/s/nt/l/pe-l/lwdl 2.5/3/s/nt/l/pewdk

2.5/blz/5.08/zatnhe wsi6 60-150v dc/actnhe wsi6/ld 250acwpo 4wdu 16nwdu 16n blwdk 2.5pewdk 2.5du-pewdu 4  
wswdu 4 orwdu 2.5 wswdu 2.5 ts wa 2.4wpe 70/95wff 120/3/bwdu 2.5 pa/viwdu 2.5 brwdu 2.5 grwdu 4 grwdu 4 brwdu  
4 pa/viwdk 2.5 bla/5.08/zawdk 2.5 blz/7.62/zawdu 2.5/blz/7.62wdu 6 grwdu 2.5 ge/gnwtr 2.5/zzwtr 2.5/zz blwdu 2.5n  
ge/gnwdu 4 ge/gnwdu 6 ge/gnwdu 6 gewdu 35nwdu 35n blwdu 2.5n zqvwdk 2.5n zqv blwdk 2.5 zqvwdk 2.5 zqv  
blwdk 2.5 2rwdu 2.5/tc typ nwdk 2.5nwdk 2.5n vwdk 2.5n pewdk 2.5n du-pewdk 2.5n blwdk 4nwdk 4n vwdk 4n  
pewdk 4n ewdk 4n du-pewdk 4n orwdk 4n blwdu 10 -wdu 10/zrwdu 10/zr blwpe 10/zrwdu 4nwdu 4n blwpe 4nwew  
35/2 -wap 2.5-10wap 2.5-10 swwap 2.5-10 gewap 2.5-10 rtwap 2.5-10 grwap 2.5-10 orwap 2.5-10 brwap 2.5-10 blwap  
2.5-10 wswap 16 35 wtw 2.5-10wap 16 35 wtw 2.5-10 orwap 16 35 wtw 2.5-10 blwhp 2.5-35n/10x3whp 2.5-35n/10x3  
blwhp 2.5-10/6x6 blwta 5/1wqv 4/2wqv 4/10kisc m3x5wqv 6/10wqv 6/2wqv 10/10wqv 10/2wqv 35/2wqv 35/2 blwqv  
35/10wqv 16/2wqv 16/2 blwqv 16/10wqv 2.5/2wqv 2.5/3wqv 2.5/4wqv 2.5/5wqv 2.5/6wqv 2.5/7wqv 2.5/8wqv  
2.5/9wqv 2.5/10wqv 4/3wqv 4/4wqv 6/3wqv 6/4wqv 10/3wqv 10/4wqv 16/3wqv 16/4wqv 35/3wqv 35/4ls 2.8  
wdu2.5-10vh 12.2/4/2.6 wdu2.5wql 2/wdu10-2.5wqv 4/6wqv 4/7wqv 4/13wqv 4/15wqv 4/5wqv 4/8wqv 4/9wqv  
4/12wsd 2.5/d /- wtr2.5wsd 2.5/d-/ wtr2.5wsd 2.5/drbr wtr2.5wsd 2.5/scan wtr2.5wtw enwew 35/1wap wdk2.5wap  
wdk2.5 gnwap wdk2.5 blwqv 2.5/12wqv 2.5/14wqv 2.5/15wqv 4/19wap wdu2.5n/4nwap wdu2.5n/4n orwap  
wdu2.5n/4n blwap wdu2.5n/4n gewqb-pen 35wqb-pen 16wqb-pen 10wew 35/2vh 19/4/2.8 wdu2.5bfsc m2.5x25wta  
5/10wqv 6/5wqv 6/6wqv 6/7kisc m2.5x4.5wqv 120/2wqv 120/3wqv 70/95/2wqv 70/95/3kisc m6x16-z3wqv 16-2.5wqv  
16-4/6wqv 35-2.5wqv 35-4/6wah 35 hgwah 35wah 35 blwah 70 hgwah 70 bewah 70 blwah 120 hgwah 120wah 120  
blwah 185/300 hgwah 185/300 bewah 185/300 blwql 2 wff35wql 2 wff70wql 2 wff120wql 2 wff185wql 2 wff300wql 3  
wff35wql 3 wff70wql 3 wff120wql 3 wff185wql 3 wff300wza d70/95wza d120wzaf 70wzaf 120wzaf 185wzaf 300wtw  
wff35wtw wff70wtw wff120wtw wff185/300wqv 2.5/30wew 32/1wew 1/32 lcp/nawap wdl2.5/swap wdl2.5whp wdl2.5/s  
blwqv 35-10wbb wdu1.5/bl...wbb za wdu1.5/bl 10/10wap wtl6/1wtw wtl6/1 dbwsh 1wap wff35wap wff70wds 2wap  
wdk2.5/blz/o.zawap wdk2.5/blz/m.zawzaf 35stb 21.6/ih/db wtl6/3stb 21.6/ih/ge wtl6/3stb 21.6/ih/gn wtl6/3stb  
21.6/ih/vi wtl6/3stb 21.6/ih/sw wtl6/3stb 21.6/ih/bl wtl6/3zr wpo4 dbssch 7.3x1.2x1000wqv 16n-pen blq 2 wdl2.5sq 3  
wdl2.5sq 4 wdl2.5sq 10 wdl2.5sew 15/2wad 4 ge bedwad 4 wswap 2.5-10 gnwap 2.5-10 viwqv 70/95-penwqv  
120-penwqv 16n-4/6wbb wdk2.5/bl5.08wbb za wdk2.5/bl5.08wap wff120wqv 16n-2.5wad 12n ge bedwad 12n wswqv  
16n-10wzr wdk2.5q 20 wdl2.5swap wtr2.5/zzwap wtr2.5/zz blwqv 35n/2wqv 35n/3wqv 35n/4wqb pen 35nwqb pen  
16nwqb pen 70nwsh 4 mtwsh 5wsh 6bs 35/wshbfch 1/wshwsh 18 mtwsh 19 mtwad 16n wswad 16n ge bedsmse wsh  
u1wap wdk2.5/4 nwap wdk2.5/4 n blsakh 10 cun/ep/swsakl 4/en 10r potisakl 4/en 30r potisakl 4/en 50r potisakl 4/en  
500r potisakl 4/en 1k potisakl 4/en 2k potisakl 4/en 5k potisakl 4/en 10k potisakl 4/en 50k potisakl 4/en 100k potisakl  
4/en 500k potidk 4/35 gl 1d i1,0asaks 1/35 g20 ld 24vacdk 4/32 ld 1d 230vacdk 4/35 ld 1d 230vacdk 4/35 gtsesakl 4/en  
t 100r potisakl 4/en t 1k potisakl 4/en t 10k potisakl 4/en t 100k potisakt e/35 2ld 30vacdk 4q/d/35 g.smsezb 10  
f.10x3/10x5/10x10tw sak4-10hp nt16/10x3sakt 4/35/lt o.stbsakt 4/35/lt stb2.0fzs 2/4 rt/80 sakt4dk 4q/35/tc typ jdk  
4q/35/tc typ kdk 4q/35/tc typ ttst 2/m5tbs 2sakt 4/35/lt stb2.3ake 2.5dkt 4v 2stbdkt 4v/35 2stbdkt 4/35 sl 2stbdkt 4 sl  
2stbq 2 dliq 3 dliq 4 dliq 5 dliq 10 dliap dli2.5dli 2.5dli 2.5/ld-rt/pnp -nsch 2mkisc m2.5x8/2.5 dli2.5dld 2.5ap dld2.5ap  
dld2.5 blmk 3/6 so brinkmannqvs 2/4 sakt4ssp 4 sakt4sak 4/35 ordk 4q/10 bez1-9sak 2.5 ortw/ap ak4ss 8/35 bz28  
pa/swss 10/35 bz28 pa/swss 12/35 bz32 pa/swap tw/ss.../35wsa 2/top/fuewsa 2/top/fue/rhdk 4q/tc typ jdk 4q/tc typ tdk  
4q/tc typ kek 70/35/m.2zb o.ikbst 4 rt sakc4vh 4.2/4/2.8 dli2.5ql 2/ss12ql 2/ss8 10avr 4/10 2.4 seavr 4/10 2.4 se blhev  
ask1saks 2/35 dbsaks 2/35adp 4/300avr 4/10 se 1.6ep 1/bw sakg32/35 hp/dbteap dld2.5ssch 10x3x2000 cu verz.ap  
dk4qap dk4q blzbl 35 lp-anschlussq 20 dliakc 10/35 1stb4 krgsak 10/35 2 stb4 krgadp 4/1000ew 35/soakz 4/atarv  
16/25 2.4/1x1dla 2.5fksc m4x6 d8/sw2q 20 akz4dk 4/35/800vwdk 2.5 tt se 2.4wdu 1.5/blawdu 1.5/bla/ld 24vwdu  
1.5/bla/rwap wdu1.5/blz/zawap wdu1.5/blz/wdu 1.5/blz 5.08wdu 1.5/blz/ld 5.08 12vwdu 1.5/blz/ld 5.08 24vwdu  
1.5/blz/ld 5.08 48vwdu 1.5/blz/r 5.08wad wdu1.5/blwqv 2.5/20wqv 2.5/32dla 2.5/ddla 2.5/ld-gndla 2.5/ld-rt/ddli  
2.5/ld-rt/pnp -ql 3/ss8 10wqb a/2wqb a/3wqb a/4wqb a/6wqb a/10wqb a/24wqb b/2wqb b/3wqb b/4wqb b/6wqb  
b/10wqb b/24tw ts15/exklbue 4-13.5siha ask1 kanada rtsta 2.5/1 m.apwdu 1.5/blz5.08/32zbsc wdu2.5/m2.5zbsc  
sak2.5zbsc sak4/m3zb sak6nzb sak10zbsc sak10zb sak16zb wdu16zbsc wdu16/m5zb sak35nzb sak35zbsc sak35dld  
2.5/peap dld2.5/pete dld2.5/pesakh 35 ep/swsakk 4 ker/wssakk 10 ker/wsklbue 3-8klbue 10-20ssp wtl6/2wks 1/2wkb  
1/2wks 1/3wkb 1/3wks 1/4wkb 1/4wkb 1/10zdu 2.5zdu 2.5 blzdu 2.5/3anzdu 2.5/3an blzdu 2.5/4anzdu 2.5/4an blzdu  
2.5/2x2anzdu 2.5/2x2an blzdu 6zdu 6 blzpe 2.5zpe 2.5/3anzpe 2.5/4anzpe 6ztr 2.5ztr 2.5 blztr 2.5/o.tnheztr  
2.5/dzap/tw 1zap/tw 1 blzap/tw 1 orzap/tw 2 dbzap/tw 2 blzap/tw 2 orzap/tw 3zap/tw 3 blzap/tw 3 orzap/tw 5zap/tw 5  
blzap/tw 5 orzqv 2.5/2zqv 2.5/3zqv 2.5/4zqv 2.5/5zqv 2.5/6zqv 2.5/7zqv 2.5/8zqv 2.5/9zqv 2.5/10zqv 4/2 gezqv 4/3  
gezqv 4/4 gezqv 4/5 gezqv 4/6 gezqv 4/7 gezqv 4/8 gezqv 4/9 gezqv 4/10 gezta 1zta 1/zazta 2 zdu4zta 2/za

zdu4zad 2/4zad 1/4zad 3/4sv 2/35tstw d 4.3zap tnhe/zi2.5zqw 1zqw 2zrh 2.5/3zrh 2.5/2 gr/v0zrh 2.5/1 wsmak 2.5ap  
mak2.5wfl 120/150zsi 2.5zsi 2.5/ld 250aczi 2.5/ld 120aczi 2.5/ld 60aczi 2.5/ld 28aczi 2.5/2 500aczi 2.5/2/ld 28aczi  
2.5/2/ld 60aczi 2.5/2/ld 120aczi 2.5/2/ld 250aczu 2.5/10zdu 2.5/3an/10zdu 2.5/4an/10zqv 6/2 gezqv 6/3 gezqv 6/4  
gezdu 6/10mak 2.5/spzwd 6/1 rtwd 6/1 gewtd 6/1 swwd 6/1 blzdu 4zdu 4 blzpe 4zap/tw 4zap/tw 4 blzap/tw 4 orzrh  
1.5n/2zrh 1.5n/1ze 1wta 1 wdu1.5wta 1/za wdu1.5wta 2 wdu2.5-10wta 2/za wdu2.5-10wta 2/10  
wdu2.5/10wta 3 wdu4wta 3/za wdu4wta 3/10 wdu4/10wta 6 wtr2.5wta 6/za wtr2.5sta 1/za sak4-10ata  
1/za akz4zqs 2.5/2zqs 2.5/3zqs 2.5/4zqs 2.5/5vli 1.5ap vli1.5vqb 1.5/50 blvqb 1.5/50 rtvli 1.5/peap vli1.5/petead 1  
mak2.5vqb 1.5/50 swwqv 16n/2wqv 16n/3wqv 16n/4zrh 4/1 wszrh 4/2zrh 4/3zdu 2.5 orzdu 2.5/3an orzdu 2.5/4an  
orzdu 2.5/2x2an orzdu 6 orzdu 4 orztr 2.5 orzza 2.5zvl 1.5zza 2.5/zazap/tw zia1.5/3lzap/tw zia1.5/4lsta 4  
dk4/dk4qwa 4wta 7 wsi6zdu 2.5/2x2an/dzdu 2.5/2x2an/d-zvl 1.5 blzvl 1.5 brzbw 2zbw 3zbw 4zbw-6zdu  
4/10/bezzvl 1.5/pe gn/ge bedzia 1.5/3l-1szia 1.5/3l-1s/ldzia 1.5/3l-pezia 1.5/4l-1szia 1.5/4l-1s/ldzia 1.5/4l-pezia  
3 zdu6ztr 2.5/3anqs 2/10/4 o.stgfzwb 1zbwwztr 2.5/3an blztr 2.5/3an/o.tnheztr 2.5/3an orztr 2.5/3an/dqvs 2  
sakt1zdk 2.5zap/tw zpv1.5zap/tw zdk2.5fta 2.5klbue 2x2-6bzt zvl1.5bzt zvl1.5/o.zazpv 1.5zduszb 2.5-2akz 4/2/tc typ  
kzap-ma/2sq zvl1.5zdk 2.5 blfk 4zstzrh 1.5h/2zrh 1.5h/1zdu 2.5 rtzdu 2.5 gezdu 2.5 gnzdu 2.5 vizdu 2.5 brzdu 2.5  
grzdu 2.5 wszdu 2.5 swzdu 2.5/3an rtzdu 2.5/3an gezdu 2.5/3an gnzdu 2.5/3an grzdu 2.5/3an wszdu 2.5/3an swzdu  
2.5/4an rtzdu 2.5/4an gezdu 2.5/4an gnzdu 2.5/4an brzdu 2.5/4an grzdu 2.5/4an wszdu 2.5/4an swzdu 4 rtzdu 4 gezdu  
4 brzdu 4 grzdu 4 wszdu 4 swzap/tw 1 rtzap/tw 1 gnzap/tw 1 grzap/tw 2 gnzap/tw 2 wszap/tw 3 rtzap/tw 3 gezap/tw 3  
gnzap/tw 3 grzap/tw 3 wszap/tw 3 swzap/tw 4 gnwqv 16n/2 blzta 4zkbd 2.5/1.5zkbd 2.5/1.5pezsl 2.5/1.5/2zsl  
2.5/1.5/3zap zkbd/zksdzap zkbd/zksd orzvr zbl/zslzsl 2.5/1.5/4zsl 2.5/1.5/5zsl 2.5/1.5/6zsl 2.5/1.5/7zsl  
2.5/1.5/8zsl 2.5/1.5/9zsl 2.5/1.5/10zsl 2.5/1.5/12zdk 2.5n-duzdk 2.5du-pezdk 2.5n-pezdk 2.5vzdk 2.5pezdk 2.5/ld  
rt/1zdk 2.5/d/1zdk 2.5/d/2zdk 2.5/d/4zdk 2.5/d/5zdk 2.5/d/6zap/tw zdk2.5 orzdu 2.5/4an ge/gnklbue 3-8 sczdu  
2.5/2x2an/ldzdu 2.5/2x2an/ld-zia 1.5/3l-1s/10zia 1.5/4l-1s/10zia 1.5/3l-1s/8/kbia 1.5/3l-1s/16/kbia 1.5/3l-  
pe/8/kbia 1.5/3l-pe/16/kbia 1.5/4l-pe/8/kbia 1.5/4l-pe/16/kbzqv 2.5n/2 gezqv 2.5n/3 gezqv 2.5n/4 gezqv 2.5n/5  
gezqv 2.5n/6 gezqv 2.5n/7 gezqv 2.5n/8 gezqv 2.5n/9 gezqv 2.5n/10 gezqv 2.5n/50 gezdk 2.5/ld rt/2zdk 2.5  
orklbue-4-6zzqv 2.5/50zksd 2.5/1.5zksd 2.5/1.5pezbl 2.5/1.5/2zbl 2.5/1.5/3zbl 2.5/1.5/4zbl 2.5/1.5/5zbl  
2.5/1.5/6zbl 2.5/1.5/7zbl 2.5/1.5/8zbl 2.5/1.5/10zbl 2.5/1.5/12zvl 1.5/pe gnzpes 2.5/4an wszrv 1.5zrv 1.5zrv  
1.5/peap zrv1.5 dbap zrv1.5 dbstgh 4 zrv1.5stgh 4 zrv1.5/pe gnstgh zrv1.5/pe gnzdu 4 ge/gnzdu 2.5 ge/gnzdu 2.5/3an  
ge/gnzdkb 2.5/1.5zdk 2.5/1.5zap zdkb/zdksztw zdubzdub 2.5-2/2an/dmzdub 2.5-2/2an/dm blzdub 2.5-2/2an/dm  
orzdu 2.5-2/2an/dm gezdu 2.5-2/2an/2/dbzdub 2.5-2/2an/3/dbzdub 2.5-2/2an/6/dbzdub 2.5-2/2an/dbzdub  
2.5-2/2an/db blzdub 2.5-2/2an/db orzdu 2.5-2/2an/db gezdu 2.5-2/4an/dmzdub 2.5-2/4an/dm blzdub  
2.5-2/4an/dm orzdu 2.5-2/4an/dm gezdu 2.5-2/4an/dbzdub 2.5-2/4an/db blzdub 2.5-2/4an/db gezdu 2.5-2/4an/db gezdu  
zduzap zdu zap zdu blzap zdu ordffc 0.2-0.35 zrv1.5dffc .5-1.0 zrv1.5dffc .2-.35 zrv1.5dffc .5-1.0 zrv1.5erwz zrv1.5zdu  
2.5-2/3anzdu 2.5-2/3an blzdu 2.5-2/3an orzdu 2.5-2/4anzdu 2.5-2/4an blzdu 2.5-2/4an orzpe 2.5-2/3anzpe  
2.5-2/4anzap/tw7zap/tw7 blzap/tw7 orzvl 1.5 o.qvklbue 4-13.5 scklb? 4-13.5 sc m4x16klbue 10-20 sczdu  
2.5-2/2an/15zdub 2.5-2/2an/15 blzdub 2.5-2/2an/15 orzdu 2.5-2/4an/15zdub 2.5-2/4an/15 blzdub 2.5-2/4an/15  
orzpe 2.5-2zdub 2.5-2/2an/rczdub 2.5-2/2an/rc blzdub 2.5-2/2an/rc orzdu 2.5-2/2an/rc gezdu 2.5-2/4an/rczdub  
2.5-2/4an/rc blzdub 2.5-2/4an/rc gezdu 2.5/d/8ql 3 ss10/2xss6zdu 2.5-2/2an/2/15zvl 1.5 invzvl 1.5 inv blzvl 1.5 inv  
brzdk 2.5/d/0wsh 3/h/nsak 4klbue 15-32wpe 35nzqv 2.5n/2 rtzqv 2.5n/3 rtzqv 2.5n/4 rtzqv 2.5n/5 rtzqv 2.5n/6 rtzqv  
2.5n/7 rtzqv 2.5n/8 rtzqv 2.5n/9 rtzqv 2.5n/10 rtzqv 2.5n/2 blzqv 2.5n/3 blzqv 2.5n/4 blzqv 2.5n/5 blzqv 2.5n/6 blzqv  
2.5n/7 blzqv 2.5n/8 blzqv 2.5n/9 blzqv 2.5n/10 blzqv 2.5n/2 swzqv 2.5n/3 swzqv 2.5n/4 swzqv 2.5n/5 swzqv 2.5n/6  
swzqv 2.5n/7 swzqv 2.5n/8 swzqv 2.5n/9 swzqv 2.5n/10 swzqv 2.5n/50 rtzqv 2.5n/50 blzqv 2.5n/50 swklbue 15-32  
sczld 2.5-2zap zld 2.5-2tw kst5-12 re/no 160/hmwnt 35n 10x3zvr 3zvr 1zvr 2zvq 2.5/1.5zdl 2.5s/nt/l/pezdl 2.5  
s/l/lzdl 2.5 s/nzdl 2.5 s/lzdl 2.5 s/n/lzdl 2.5 s/n/l/pezdl 2.5 s/l/l/pezdl 2.5/nt/l/pezdl 2.5/l/lzdl 2.5/nzdl 2.5/lzdl 2.5/n/lzdl  
2.5/n/l/pezdl 2.5/l/l/pezhp zdl2.5s blzap zdl2.5zap zdl2.5zdua 2.5-2zdua 2.5-2 blzdua 2.5-2 orzpea 2.5-2zap/tw  
zduazap/tw zdua blzap/tw zdua ormofu 15/35 zdubbs 35ii klbue holderbs 35ii klbue3-8bs 35ii/klbue 4-13.5fm  
4.2/ts35zk3szdu 2.5/10/bez/o.zazdu 4/10/bez/o.zazsl 2.5/1.5/15zbl 2.5/1.5/15zsi 2.5/5x25wdu 2.5n/600ulzap  
zdk4/6szdk 6s/ntzdk 6s/l/lzdk 6s/l/pezdk 4s/ntzdk 4s/l/lzdk 4s/l/pezdk 4s/nzdk 4s/n/lzdk 4s/n/pezdk 6s/nzdk  
6s/n/lzdk 6s/n/pezqv 6/32 geglmu m4 klbuebbb zdub blzdu 10szdu 10s blznt 10szpe 10szdu 16szdu 16s blznt 16szpe  
16szdu 35zdu 35 blznt 35zpe 35zap zdu10/16szqv 10/2zqv 16/2zqv 35/2zpe 2 zbl/zsldzpe 4 zbl/zsldzpe 8  
zbl/zsldzap zkb/zkszks 2.5/1.5zkb 2.5/1.5btwz klbuezd 2.5/tr/du/pezdl 2.5/tr/duzap/tw zdu16zap/tw zdu16 orzhp  
z/w blzad 5/5zdu 16zdu 16 blzpe 16zei 16zdr 2.5ap zdr2.5zdk 2.5v blssch 10x3x1000 st/znkib? 4-13.5 sc m4x6zad

4/5zdu 10zdu 10 blzpe 10zap zkb/zks orts 35x7.5 2m/crnzap/tw zdu10zap/tw zdu10 orzap/tw zdk2.5 blklbue co  
3klbue co 4bs 35ii klbue3-8/2x2-6zap/tw 10/16zap/tw 10/16 orask 1/en dbklbue co 2zad 6/5klbue 3-8 cpf ssklbue  
4-13.5 cpfklbue 10-20 cpfklbue 15-32 cpftw kst5-12 li/no 160/hmwdu 1.5/r3.5wdk 1.5/r3.5klbue co 1ap ask1 dbwdu  
2.5 pa/dblwdu 1.5/r3.5 blwdk 1.5/r3.5 blwap wdu1.5/r3.5wap wdk1.5/r3.5zqv 1.5n/r3.5/2 gezqv 1.5n/r3.5/3 gezqv  
1.5n/r3.5/4 gezqv 1.5n/r3.5/5 gezqv 1.5n/r3.5/6 gezqv 1.5n/r3.5/7 gezqv 1.5n/r3.5/8 gezqv 1.5n/r3.5/9 gezqv  
1.5n/r3.5/10 gezqv 1.5n/r3.5/30 gewtl 4wtl 4/stbklbue co 5zdu 4/ntzqv 4n/2 gezqv 4n/10 gezqv 4n/41bs 35/wsh 2zdu  
10/ntzqv 4n/4 gezqv 4n/3 gezdl 2.5/si/du/pezdl 2.5/si/duzdl 2.5/si/du/pe ld 36vzdl 2.5/si/du/pe ld 70vzdl 2.5/si/du/pe  
ld150vzdl 2.5/si/du/pe ld250vzdl 2.5/si/du ld 36vzdl 2.5/si/du ld 70vzdl 2.5/si/du ld 150vzdl 2.5/si/du ld 250vwtr  
2.5/siwtr 2.5/si ld 36vwtr 2.5/si ld 70vwtr 2.5/si ld 150vwtr 2.5/si ld 250vztr 2.5/siztr 2.5/si ld 36vztr 2.5/si ld 250vzap/tw  
zdu16 blzap/tw zdu10 blzbs1 setzbs1 f.d setzad 1/4-2 gezei 16 blwtw wtl 6/1 4mmzpe 10/3anzdu 10/3anzdu 10/3an  
blzmak 2.5zap zmak2.5zpe 16/3anzdu 16/3anzdu 16/3an blzap/tw 10/16 blzdk 2.5 emzdu 4-2/3anzdu 4-2/2anzpe  
4-2/2anzpe 4-2/3anzap zdu4-2zdu 4-2/2an blzdu 4-2/3an blzdu 4-2/3an orzap zdu4-2 blzap zdu4-2 orzpe 6-2/3anzpe  
6-2/2anzdu 6-2/2anzdu 6-2/2an blzdu 6-2/3anzdu 6-2/3an bl

本产品的加工定制是否，品牌是魏德米勒Weidmüller，型号是SAK系列W系列Z系列，应用范围是电缆，  
种类是端子(TERMINAL),端子(TERMINAL)，接口类型是AC/DC，支持卡数是单卡，读卡类型是CF，形  
状是条形，制作工艺是冷压，特性是防潮，工作频率是低频，接触件材质是铜，绝缘体材质是尼龙，芯  
数是1，针数是2，线长是10（mm），吸合电流是20A，电流性质是交直流输入电路，触点形式是常闭型