

科比变频器维修

产品名称	科比变频器维修
公司名称	上海芯维自动化科技有限公司
价格	面议
规格参数	品牌:科比 型号:07F5B3A-0A00
公司地址	上海市奉贤区南桥镇金齐路188弄
联系电话	021-31606878 18679441819

产品详情

科比变频器维修、keb变频器维修、可修复科比变频器常见故障：无显示、缺相、过流、过压、欠压、过热、过载、接地、参数错误、有显示无输出、模块损坏等；combivert f4-s: 05f4s1d-m420,06f4s1d-m420,07f4s1d-m420,08f4s1d-m420,09f4s1d-m420,10f4s1d-m420,11f4s1d-m420, 12f4s1d-m420,13f4s1d-m420,14f4s1d-m420; combivert r4-s: 12r4s0g-3201,15r4s0g-3201,14r4s0g-3401,18r4s0g-3401,22r4s0r-3401; combivert f4: 07f4c1g-3240,09f4c1g-3240,10f4c1g-3240,13f4c1g-3240,14f4c1g-3240,15f4c1g-3240,16f4c1g-3240,17f4c1g-3240,18f4c1g-3240,19f4c1g-3240,20f4c1g-3240,21f4c1g-3240,07f4c1g-3440,09f4c1g-3440,10f4c1g-3440,13f4c1g-3440,14f4c1g-3440,15f4c1g-3440,16f4c1g-3440,17f4c1g-3440,18f4c1g-3440,19f4c1g-3440,20f4c1g-3440,21f4c1g-3440; combivert f4-c: 07f4c1d-1280,07f4c3d-1280,10f4c1d-1280,10f4c3d-1280,09f4c1d-1220,09f4c3d-1220,13f4c1e-3220,13u400e-ba01,14f4c1g-3280,14u400g-ba01,15f4c1h-3280,15u400h-ba01,16f4c1h-3280,16u400h-ba01,07f4c1d-3420,07f4c3d-3420,09f4c1d-3420,09f4c3d-3420,10f4c1d-3460,10f4c3d-3460,12f4c1d-3420,12f4c3d-3420,13f4c1d-3410,13f4c3d-3410,14f4c1e-3440,15f4c1e-3420,14u400e-bm01,15u400e-bm01,16f4c1g-3440,17f4c1g-3420,16u400g-bm01,17u400g-bm01;18f4c0h-3440,19f4c0h-3420,18u400h-bm01,19u400h-bm01,20f4c0r-3440,20f4c2r-3440,21f4c0r-3420,21f4c2r-3420,22f4c0r-3420,22f4c2r-3420,23f4c0r-3410,23u40ru-bm01,24f4c0u-3420,25f4c0u-3420,25u400u-bm01,27f4c0u-3410,26f4c0u-3410,27u400u-bm01,28f4c0w-3410,28u4w-3000,29f4c0w-3410,29u4c0w-3000,30f4c0w-3410,30u4c0w-3000; combivert f4-f: 07f4f1d-3240,07f4f3d-1240,10f4f1d-3440,10f4f3d-3440,14f4f1e-3440,12f4f1e-3440,13f4f1e-3440,14u400e-bm01,15f4f1g-3440,16f4f1g-3440,16u400g-bm0,117f4f1h-3440,18f4f1h-3440,18u400h-bm01,19f4f1r-3440,19f4f3r-3440,20f4f1r-3440,20f4f3r-3440,21f4f1r-3440,21f4f3r-3440,22f4f1r-3440,22f4f3r-3440; combivert r4-f: 14r4f0g-3241,16r4f0g-3440,20r4f0r-3440; combivert f5-b:05f5b3a-0a00,07f5b3a-0a00,09f5b1b-2b00,10f5b1b-2a00,12f5b1d-1a00,13f5b1e-1600,14f5b1e-1500,05f5b1b-3b00,07f5b1b-3b00,09f5b1b-3b00,10f5b1b-3a00,12f5b1b-3500,13f5b1d-3900,15f5b1e-3900,14f5b1e-3a00,16f5b1g-3600,17f5b1g-3500,18f5b0h-3600,19f5b0h-3500; combivert m4:07m4c0d3220,09m4c0d3220,07m4c0d3420,09m4c0d3420,10m4c0d3420,11m4c0d3420; combivert f5-g:05f5g1b-2b00,07f5g1b-2b00,09f5g1b-2b00,10f5g1b-2a00,12f5g1d-1a00,13f5g1e-1600,14f5g1e-1500,15f5g1g-1500,16f5g1h-1700,17f5g1h-1600,18f5g0r-7700,19f5g0r-7600,20f5g0r-7600,21f5g0u-7200,22f5g0u-7200,23f5g0u-7100,05f5g1b-3b00,07f5g1b-3b00,09f5g1b-3b00,10f5g1b-3a00,12f5g1b-3500,13f5g1d-3900,14f5g1e-3a00,15f5g1e-3900,16f5g1g-3600,17f5g1g-3500,18f5g0h-3600h,19f5g0h-3600h,20f5g0r-9600,21f5g0r-9500,22f5g0r-9500,23f5g0r-9400,24f5g0r-9400,25f5g0u-u9100,26f5g0uu-9100,27f5g0uu-9000,28f5g0w-9000,29f5g0ww-9000,30f5gw0w-9000; combivert r4:14r4s0g-3401,18r4s0g-3401,22r4s0r-3401,16r4f0g-3440,21r4f0r-3440; combivert f5-m/s:09f5m1d-2b010f5m1d-2a_

0,12f5m1d-1a_0,13f5m1e-16_0,14f5m1e-15_0,15f5m1g-15_0,16f5m1h-17_0,17f5m1h-16_0,18f5m1r-77_0,19f5m1r-76_0,20f5m1r-76_0,21f5m1u-72_0,22f5m1u-72_0,23f5m1u-71_0,09f5m1d-3a_0,10f5m1d-39_0,12f5m1d-3a_0,13f5m1d-39_0,14f5m1e-3a_0,15f5m1e-39_0,16f5m1g-36_0,17f5m1g-35_0,18f5m1h-36_0,19f5m1h-35_0,20f5m1r-96_0,21f5m1r-95_0,22f5m1r-95_0,23f5m1r-94_0,24f5m1r-94_0,25f5m1u-91_0,26f5m1u-91_0,27f5m1u-90_0,28f5m1w-90_0,29f5m1w-90_0,30f5m1w-90_0; keb combivert f4-s:05f4s0c-1220,05f4s2c-1220,07f4s0c-1220,07f4s2c-1220,09f4s1d-1220,09f4s3d-1220,10f4s1d-1220,10f4s3d-1220,13f4s1e-3220,13u400e-ba00,07f4s1d-3420,07f4s1d-3410,07f4s3d-3420,07f4s3d-3410,09f4s1d-3420,09f4s1d-3410,09f4s3d-3420,09f4s3d-3410,10f4s1d-3420,10f4s1d-3410,10f4s3d-3420,10f4s3d-3410,12f4s1d-3420,12f4s1d-3410,12f4s3d-3420,12f4s3d-3410,13f4s1d-3420,13f4s1d-3410,13f4s3d-3420,13f4s3d-3410,14f4s1e3400,15f4s1e3200