

??	??(kw)	??		d	d1	w	w1	h	a* b
jxl-5	1.5	5a	2%	110	91	120	65	135	6*11
jxl-7	2.2	7a	2%	110	91	120	65	135	6*11
jxl-10	3.7	10a	2%	155	95	110	61	155	6*15
jxl-15	5.5	15a	2%	155	95	130	80	155	6*15
jxl-20	7.5	20a	2%	155	95	135	80	155	6*15 zs
jxl-30	11	30a	2%	190	120	115	85	150	8.5*20
jxl-40	15	40a	2%	195	120	110	82	165	8.5*20
jxl-50	18.5	50a	2%	195	120	130	102	165	8.5*20

jxl-60	22	60a	2%	195	120	135	107	165	8.5	*20
jxl-80	30	80a	2%	195	120	135	107	165	8.5	*20
jxl-90	37	90a	2%	195	120	135	107	165	8.5	*20
jxl-120	45	120a	2%	250	182	135	96	230	11	*18
jxl-150	55	150a	2%	295	214	150	110	240	11	*18
jxl-200	75	200a	2%	295	214	160	120	240	11	*18
jxl-250	110	250a	2%	295	214	160	120	240	11	*18
jxl-290	132	290a	2%	325	243	165	122	270	12	*20

jxl-330	160	330a	2%	325	243	165	122	270	12*20
jxl-400	185	400a	2%	325	243	180	137	270	12*20
jxl-490	220	490a	2%	385	260	200	175	350	12*20
jxl-600	280	600a	2%	395	275	200	175	350	12*20
jxl-660	300	660a	2%	395	275	200	175	350	12*20
jxl-800	380	800a	2%	430	295	215	190	400	12*20
jxl-1000	450	1000a	2%	430	295	215	190	450	12*20
jxl-1200	550	1200a	2%	490	345	225	195	575	14*25

jxl-	55	12	4%	470	34	23	20	58	12
12	0	00			5	0	5	0	*2
00		a							2