

?????	????	???	???? ???	?? (mm)	????? ?0.5(?)
?????	WZP?120	Pt100 (Pt10)	-200~500 (-200~650)	?16	?90
	WZP?121			?12	?45
	WZP?130			?16	?90
	WZP?131			?12	?45
?????	WZP2?120	Pt100 (Pt10)	-200~500 (-200~650)	?16	?90
	WZP2?121			?12	?45
	WZP2?130			?16	?90

	WZP2?131			?12	?45
????	WZC?120	Cu50 (Cu100)	-50~150	?12	?120
	WZC?130				

?????????????? ?120?121??????????130?131???????? b????????? ??????????????

?????	????	???	???? ???	?? (mm)	????? ?0.5(?)
?????	WZP?220	Pt100 (Pt10)	-200~500 (-200~650)	?16	?90
	WZP?221			?12	?45
	WZP?230			?16	?90
	WZP?231			?12	?45

?????	WZP2?220	Pt100 (Pt10)	-200~500 (-200~650)	?16	?90
	WZP2?221			?12	?45
	WZP2?230			?16	?90
	WZP2?231			?12	?45
????	WZC?220	Cu50 (Cu100)	-50~150	?12	?120
	WZC?230				

????????????? ?220?221?????????230?231???????

??M0?27x2mm????M0?G3/4"?????????????WZP??220A?

c????????? ????????????

?????	????	???	???? ???	?? (mm)	????? ?0.5(?)

?????	WZP?320	Pt100 (Pt10)	-200~500	?16	?90	
				(-200~650)		
	WZP?321				?12	?45
?????	WZP?330	Pt100 (Pt10)		?16	?90	
	WZP?331				?12	?45
?????	WZP2?320	Pt100 (Pt10)	-200~500	?16	?90	
				(-200~650)		
	WZP2?321				?12	?45
?????	WZP2?330	Pt100 (Pt10)		?16	?90	
	WZP2?331				?12	?45
????	WZC?320	Cu50 (Cu100)	-50~150	?12	?120	

	WZC?330				
--	---------	--	--	--	--

?????????????? ??320?321??????????330?331????????

d?????????? ??????????????

?? ??	????	???	???? ???	?? (mm)	??????0.5(?)
?? ???	WZP-420	Pt100 (Pt10)	-200~500 (-200~650)	??16	??90
	WZP-421			??12	??45
	WZP-430			??16	??90
	WZP-431			??12	??45
?? ???	WZP2-420	Pt100 (Pt10)	-200~500 (-200~650)	??16	??90

	WZP2-421			?12	?45
	WZP2-430			?16	?90
	WZP2-431			?12	?45
?? ??	WZC-420	Cu50 (Cu100)	-50~150	?12	?120
	WZC-430				

[WZP-270?????? ??????????](#)

?????????????? ?????A?B ?????IP65 ?????d?BT4.d?CT5 3???????

??	???	?????	?????	?????	??
WZP-260	Pt100	0-100	?30S	1Cr18Ni9Ti	100

WZP2-260			?45S
WZP-267M	Pt100	-50-+150	?30S
WZP-269	Pt100	-200-+300	?30S
WZP2-269			?45S
WZC-269	Cu50	-50-+100	?120S
WZP-270	Pt100	-200-+420	?15S

150
200
250
300
75
100
150
200
250
50
75
100
150

WZC-270	Cu50	-50-+150	?45S	200
WZP-280	Pt100	-200-+300	?30S	