

X/Y/Z?????X/Y/Z rapid traverse speed	m/min 24/24/20(Optional:48/48/36)
?????Cutting feed speed	mm/mi1-10000
?????Guiderailtype	??Linear rail
????????????	410
Distance from spindle axis to column surface	
????????????	100-550
Distance between spindle nose and worktable surface	
????Positioning accuracy	±0.0075
?????Repeatpositioningaccuracy	±0.005
??Tool magazine	??Armless16(Optional:??Arm 24)
????Max.Tool diameter	?90
????Max.Tool weight	8
????Machine weight	3000
????Overall dimension	1900x1700x2100