

## ABB系列DCS直流调速河南区总代理，洛阳一级代理

|      |                            |
|------|----------------------------|
| 产品名称 | ABB系列DCS直流调速河南区总代理，洛阳一级代理  |
| 公司名称 | 福州盈泰自动化科技有限公司洛阳分公司         |
| 价格   | 10.00/台                    |
| 规格参数 |                            |
| 公司地址 | 洛阳市西工区中州中路178号中冠新坐标大厦2003室 |
| 联系电话 | 86-15290525991 15136350314 |

### 产品详情

ABB DCS400 系列直流调速器: DCS401.0020 DCS401.0045 DCS401.0065 DCS401.0090 DCS401.0125 DCS401.0180 DCS401.0230 DCS401.0315 DCS401.0405 DCS401.0500 DCS401.0610 DCS401.0740 DCS401.0900 DCS402.0025 DCS402.0050 DCS402.0075 DCS402.0100 DCS402.0140 DCS402.0200 DCS402.0260 DCS402.0350 DCS402.0450 DCS402.0550 DCS402.0680 DCS402.0820 DCS402.1000 DCS 401.0020 DCS 402.0025 DCS 401.0045 DCS 402.0050 DCS 401.0065 DCS 402.0075 DCS 401.0090 DCS 402.0100 DCS 401.0125 DCS 402.0140 DCS 401.0180 DCS 402.0200 DCS 401.0230 DCS 402.0260 DCS 401.0315 DCS 402.0350 DCS 401.0405 DCS 402.0450 DCS 401.0500 DCS 402.0550 DCS 401.0610 DCS 402.0680 DCS 401.0740 DCS402.0820 DCS 401.0900 DCS 402.1000 DCS 401.0020 DCS 402.0025 DCS 401.0045 DCS 402.0050 DCS 401.0065 DCS 402.0075 DCS 401.0090 DCS 402.0100 DCS 401.0125 DCS 402.0140 DCS 401.0180 DCS 402.0200 DCS 401.0230 DCS 402.0260 DCS 401.0315 DCS 402.0350 DCS 401.0405 DCS 402.0450 DCS 401.0500 DCS 402.0550 DCS 401.0610 DCS 402.0680 DCS 401.0740 DCS 402.0820 DCS 401.0900 DCS 402.1000

#### ABB DCS500直流调速器

DCS 501B0200-51,DCS 501B0250-51,DCS 501B0350-51,DCS 501B0450-51,DCS 501B0520-51,DCS 501B0680-51,DCS 501B0820-51,DCS 501B1000-51,DCS 501B1203-51,DCS 501B1503-51,DCS 501B2003-51,DCS 502B0025-51,DCS 502B0050-51,DCS 502B0075-51,DCS 502B0100-51,DCS 502B0140-51,DCS 502B0200-51,DCS 502B0250-51,DCS 502B0350-51,DCS 502B0450-51,DCS 502B0520-51,DCS 502B0680-51,DCS 502B0820-51 DCS 502B1000-51,DCS 502B1203-51,DCS 502B1503-51,DCS 502B2003-51,DCS 501B0050-61,DCS 501B0110-61,DCS 501B0270-61,DCS 501B0450-61,DCS 501B0903-61,DCS 501B1503-61,DCS 501B2003-61,DCS 501B2053-61 DCS 502B0050-61,DCS 502B0110-61,DCS 502B0270-61,DCS 502B0450-61,DCS 502B0903-61,DCS

502B1503-61,

DCS 502B2053-61,DCS 501B0903-71,DCS 501B1503-71,DCS 501B2003-71, DCS 501B2053-71,DCS 502B0903-71  
DCS 502B1503-71,DCS 502B2053-71 DSC500B DCS 501B0025-41,DCS 501B0050-41,DCS 501B0075-41,DCS  
501B0100-41,DCS 501B0140-41,DCS 501B0200-

41,DCS 501B0250-41,DCS 501B0350-41,DCS 501B0450-41,DCS 501B0520-41,DCS 501B0680-41,DCS 501B0820-41  
DCS 501B1000-41,DCS 501B1203-41,DCS 501B1503-41,DCS 501B2003-41,DCS 502B0025-41,DCS 502B0050-

41,DCS 502B0075-41,DCS 502B0100-41,DCS 502B0140-41,DCS 502B0200-41,DCS 502B0250-41,DCS 502B0350-41  
DCS 502B0450-41,DCS 502B0520-41,DCS 502B0680-41,DCS 502B0820-41,DCS 502B1000-41,DCS 502B1203-

41,DCS 502B1503-41,DCS 502B2003-41,DCS 501B0025-51,DCS 501B0050-51,DCS 501B0075-51,DCS 501B0100-

51,DCS 501B0140-51,