



测量方式	1						表压
	2						绝压
测量范围		1					0-7kpa~35kpa
		2					0-35kpa~100kpa
		3					0-50kpa~210kpa
		4					0-100kpa~350kpa
		5					0-200kpa~700kpa
		6					0-500kpa~2100kpa
		7					0-1mpa~3.5mpa
		8					0-3mpa~7mpa
		9					0-7mpa~21mpa
		10					0-15mpa~35mpa
精度等级			1				0.1%
			2				0.25%
			3				0.5%
接口方式				1			m20*15
				2			1/2"npt
防爆方式					i		本安防爆
					n		不防爆
选购件						1	带安装支架
						2	带100%线性表头