





6) : (Creep behavior) When considering the mechanical properties of any thermoplastic, the designer must recognize the influence of temperature, stress level and load duration on the material properties. PEI resin also shows excellent creep resistance at temperatures and stress levels where many other thermoplastics cannot be used.