

# 英国标准 BS 8509家用儿童床 ( 对于幼儿床, 少年床, 非婴儿床 )测试

产品名称	英国标准 BS 8509家用儿童床 ( 对于幼儿床, 少年床, 非婴儿床 )测试
公司名称	深圳市实测通技术服务有限公司
价格	.00/件
规格参数	测试周期:5-7天 寄样地址:深圳宝安 价格费用:电话详谈
公司地址	深圳市罗湖区翠竹街道翠宁社区太宁路145号二单元705
联系电话	17324413130 17324413130

## 产品详情

Test item 测试名称:

Children ' s beds for domestic use 家用儿童床 ( 对于幼儿床, 少年床, 非婴儿床 )

Test info 测试内容 :

4	General requirments整体要求
7	Mechanical hazards - gaps and openings机械伤害-缝隙和开口
8	Mechanical hazards - folding机械伤害-折叠
9	Mechanical hazards - crushing and shearing机械伤害-压迫和剪切
10	Mechanical hazards - protruding parts机械伤害-突出部分
11	Mechanical hazards - entanglement in cords, ribbons and similar parts机械伤害-绳子, 带子及类似物缠绕
12	Mechanical hazards - small parts机械伤害-小部件
13	Mechanical hazards - suffocation机械伤害-窒息
14	Mechanical hazards - edges and protruding parts机械伤害-尖角利边
15	Mechanical hazards - points and wires机械伤害-小部件
16	Mechanical hazards - inadequate structural integrity - materials and fastenings机械伤害-结构整体性缺陷-材料
17	Mechanical hazards - inadequate structural integrity - vertical static strength of bed base edges机械伤害-结构整体性缺陷-床架边缘垂直静载强度
18	Mechanical hazards - inadequate structural integrity - vertical impact strength of bed base机械伤害-结构整体性缺陷-床架边缘垂直冲击强度

	床架边缘垂直冲击强度
19	Mechanical hazards - inadequate structural integrity - durability of bed base机械伤害-结构整体性缺陷-床架
20	Mechanical hazards - inadequate structural integrity - durability of bed edge机械伤害-结构整体性缺陷-床边
21	Mechanical hazards - inadequate structural integrity - strength of head and foot boards机械伤害-结构整体性 床头与床尾板的强度
22	Mechanical hazards - inadequate structural integrity - strength of side guards and/or safety rails机械伤害-结构 床侧护板与安全栏的强度
23	Mechanical hazards - inadequate structural integrity - strength of top rails for four poster features机械伤害-结 四支柱顶部导轨的强度
24	Product Information (marking, durability of marking, purchase information, instruction for use)产品信息 ( 商标 , 商标耐用性 , 购买信息 , 使用说明 )

Lead time 测试周期: 常规 regular service 14 working days

Sample size 送样规格: 3pcs

Others 其他信息:

Photo for reference 参考图片 :