

# WPO型减速机,加工各种减速机配件，欢迎来电

产品名称	WPO型减速机,加工各种减速机配件，欢迎来电
公司名称	杭州昊峰机械有限公司
价格	110.00/台
规格参数	
公司地址	杭州市萧山区义蓬街道春光村
联系电话	86-057182166987 13336028129

## 产品详情

输出转速范围：	45 ( rpm )	齿面硬度：	硬齿面
安装形式：	卧式	加工定制：	是
减速比：	30	齿轮类型：	针轮减速机
额定功率：	250 ( kw )	型号：	WPO
使用范围：	建筑. 纺织等	布局形式：	同轴式
输入转速：	56 ( rpm )	许用扭矩：	48 ( N.m )
类别：	蜗轮蜗杆减速机	用途：	减速机
品牌：	昊峰	级数：	单级

**安装注意事项** 减速机须安装在平整坚固的底座下，底脚螺栓必须坚固、防震。原动机-减速机-工作机的各联接轴伸，安装后必须互相准确对准轴线。减速机输入端及输出端轴伸外径公差尺寸均按h6制作，与之相配的联轴器、皮带轮、链轮等传动件内孔须按合适的公差尺寸配制，避免装配过紧损坏轴承，装配过松影响正常动力传递。链轮、齿轮等传动件装上轴伸时，应尽量靠近轴承，以减少轴伸弯曲应力。wpo型减速机装配电机时，应在蜗杆头部内孔孔壁及键槽处涂抹黄油，避免装配过紧，防止轴孔日久生锈。订购使用各类wpo减速机时，若电机重量偏大，应设支撑装置。

**使用注意事项** 使用前应注意检查减速机型式结构、中心距规格、传动比、输入轴连接方式、输出轴结构、输入轴输出轴指向和回转方向等是否符合使用要求。按照样本上“润滑油的选择使用”中所规定的要求，注入合适的品种牌号润滑油。加油后，旋紧顶部的通气器，拔掉通气器上之小锥塞，减速机方可开始运转。必须选用合适牌号的润滑油，必须控制适宜的加油量，必须按规定要求及时换油，尤其要重视首次使用100小时后的更换新油。使用过程中发生不正常情况时，应及时停机检查，可参照“故障原因及解决办法”表处理。（减速机的油温最高允许达到95℃，在此温度界限下，只要油温不再上升，可以放心使用）。润滑油的选择使用choice of lubricant

蜗轮减速机使用前应注入n220 ~ n320 (环境温度-30 ~ 40 ) 或n320 ~ 460 (环境温度40 ~ 65 ) 润滑油至油标中心点上, 并取掉通气器上之小锥塞。首次使用100小时后, 洗净内部换上新油, 以后每2500小时换油一次。 before operating worm gear speed reducer, add n220 ~ n320(ambient temperature -300 ~ 40 ) ,n320 ~ n460(ambient temperature 40 ~ 65 ) lubrication oil upto the center line of the oil guage. in the mean while, remove the small screw of the air-vent. after having worked for 100 hours for the first time, must clear the inside and change the lubrication oil in it, hre after once every 2500 hours.减速机在使用时, 可按下表选用润滑油。 lubricants for a reducer used in foreign countries can be chosen from the table blowworm shaft sped(r/min) lubricant operating position worm shaft, upper worm shaft vertical oprating position worm shaft, lower output shaft verticalover upto1000 3000 synthetic oils pg460 pg2201000pg4602000 3000 mineral oils isovg460 iso vg200750 2000 iso vg320250 750 iso vg460250iso vg680 iso vg680

ambient temperaturelubricant union 76 div.union oil co. of ca agma15-60 -9-16 mineral oils spartan ep220 regal oil r&d 320 dte lil bb shell omala oil 220 union turbine oil 220 5compounded oilssparan ep320 631-honor cylinder oil mobil 600w cylinder oil shell omala oil 320 union steaval a 7extreme pressure spartan ep 460 meropa 460 mobil gears 634 shell omala oil 460 union nl lube 7ep 7ep50-125 10-52 mineral oils spartan ep320 regal oil 320 dte oil aa shell omala oil 320 union turbine oil 320 6compounded oisl spartan ep460 642-650t cylinder oil mobil 600w super cylinder oil shell omala oil 460 union worm gear lube 140 8extreme pressure spartan ep680 meropa 680 mobil gears 636 shell omala oil 660 union nl lube 8ep 8epafter the first 100 hours If operation: drain uni and flush winh ligh oil, refill.every 2500 hours If operation: drain;flush and refill.故障原因肪解决办法solutions and reasons for the general faults故障情况故障原因解决办法过热原动机、减速机、工作台连接不当调整至适当位置, 使三者相联轴线同轴超负荷运转适当调整负荷油封过度磨擦在油封唇口处滴润滑油润滑油过多或过少按油标指示点调整油量润滑油杂质多或润滑性差更换合适新油振动原动机、减速机、工作台固定不良, 连接不当查出固定不良部位, 正确固紧蜗轮副齿部磨耗或损伤更换蜗轮副轴承磨损更换轴承螺栓松脱固紧螺栓杂音轴承损伤或间隙过大更换轴承蜗轮副啮合不良修整齿面或更换蜗轮副润滑油不足按油标指示点补加润滑油机体内有异物倒净润滑油带出异物, 重加清洁润滑油漏油油封唇口磨损更换油封油封档轴颈磨损更换输出轴或输入轴油量过多按油标指示点调整油量放油螺塞未旋紧螺纹处加密封胶, 旋紧螺塞油标破损更换油标蜗轮副齿面磨损过快超负荷运转调整至适当负荷润滑油不符合要求更换合适的润滑油润滑油不足按油标指示点加足润滑油未按规定适时换油, 润滑油劣化按规定要求适时换油运转温度过高1.按“过热”故障处理2.采取合适措施, 降低环境温度 杭州萧山义蓬昊峰机械厂, 是一家专业生产各种规格升降机、减速机、以及蜗轮蜗杆配件和特制减速机的企业、地区在杭州江东开发区东侧、举世闻名的钱塘江观潮胜地南岸, 距杭州萧山国际机场15公里, 杭州萧山义蓬昊峰机械厂拥有完整、科学的质量管理体系。杭州萧山义蓬昊峰机械厂的诚信、实力和产品质量获得业界的认可。欢迎各界朋友莅临杭州萧山义蓬昊峰机械厂参观、指导和业务洽谈。