

# 郑州安川伺服驱动器维修报警C90,AC9故障的处理方法

产品名称	郑州安川伺服驱动器维修报警C90,AC9故障的处理方法
公司名称	河南远晟电气设备有限公司
价格	.00/件
规格参数	
公司地址	郑州市金水区宏明路聚福园10号楼
联系电话	18437828521 15037813007

## 产品详情

安川伺服驱动器维修报警C90,AC9故障的处理方法:一、安川伺服报警C90 ( AC9

)报警原因分析:1、编码器线缆断线或者编码器插头制作工艺不良(新机报警也有接线错误的情况);2、伺服驱动器本身故障;3、环境干扰,接不良造成:如工作环境有大功率高频干扰设备(压器,变频器)4、伺服电机编码器反馈单元故障。二、对应解决处理方法:1、检查编码器线缆是否好的,仔细检查编码线插头、焊接点及线缆弓脚排列是否正常;2、如果没发现线和插头问题,再排除编码器线缆的受干扰问题,请把编码线与其它线(动力线缆)分开;3、线是好的干扰问题也解决了,更换一条新的编码器线试下,更换后未见报警出现,后续还需跟踪1-2天;4、更换了编码器线报警还不能消除,那就把电机更换-一个上电试试看,更换后报警消除,故障的电机拿去维修中心检测;5、如果更换了电机报警还不能消除,那就把驱动器拿去检测。安川伺服驱动器维修常用故障代码A.00值数据错 值错误或没收到BC3AF CACR-PR30BC3AM CACR-PR30BC3CS CACR-PR44BC CACR-PR44BC3AF CACR-PR44BC3AM CACR-SR02BE CACR-SR02BE12F CACR-SR02BE12G CACR-SR02BE13S CACR-SR03 CACR-SR031AF CACR-SR031AM CACR-SR031ES CACR-SR031ES-Y41 CACR-SR03BE CACR-SR03BE12F CACR-SR03BE12G CACR-SR03BE12M CACR-SR03BE13S CACR-SR05 CACR-SR051AD CACR-SR051AF CACR-SR051ES CACR-SR05BE CACR-SR05BE12F CACR-SR05BE12G CACR-SR05BE13D CACR-SR05BE13S CACR-SR07 CACR-SR071AM CACR-SR07BE CACR-SR07BE12M CACR-SR10 CACR-SR101AF CACR-SR101AM CACR-SR101ES CACR-SR10BE CACR-SR10BE12F CACR-SR10BE12G CACR-SR10BE12M CACR-SR10BE13S CACR-SR15 CACR-SR151AD CACR-SR151AF CACR-SR151AM CACR-SR151ES CACR-SR15BE CACR-SR15BE12F CACR-SR15BE12G CACR-SR15BE12M CACR-SR15BE13D CACR-SR15BE13S CACR-SR20 CACR-SR201AD CACR-SR201AF CACR-SR201AM CACR-SR20BE CACR-SR20BE12F CACR-SR20BE12G CACR-SR20BE12M CACR-SR20BE13D CACR-SR30 CACR-SR301AD CACR-SR301AF CACR-SR301AM CACR-SR301ES CACR-SR30BE CACR-SR30BE12FCACR-SR30BE12G CACR-SR30BE12M CACR-SR30BE13D CACR-SR30BE13S CACR-SR44 CACR-SR441AD CACR-SR441AF CACR-SR441AM CACR-SR44BE CACR-SR44BE12F CACR-SR44BE12G CACR-SR44BE12M CACR-SR44BE13D CACR-SR60 CACR-SR601AM CACR-SR60BE CACR-SR60BE12M CDMR-MR-11K CDMR-MR-15K CDMR-MR-22K CDMR-MR-26K CDMR-MR-30K CDMR-MR-37K CDMR-MR-45K CDMR-MR-5.5K CDMR-MR-7.5K CPCR-MR01C CPCR-MR01CJ CPCR-MR02C CPCR-MR02CJ CPCR-MR02C-M CPCR-MR05C CPCR-MR05C-C CPCR-MR05C-H CPCR-MR05C-M CPCR-MR07C CPCR-MR08C CPCR-MR08C-H CPCR-MR08C-J CPCR-MR08CW CPCR-MR08CW-H CPCR-MR08CW-J CPCR-MR15C CPCR-MR15C-H CPCR-MR15C-J CPCR-MR15C-M CPCR-MR15C-P CPCR-MR15CW CPCR-

MR15CW-H CPCR-MR15CW-J CPCR-MR15CW-M CPCR-MR22C CPCR-MR22C-H CPCR-MR22C-J CPCR-  
MR22CW CPCR-MR22CW-H CPCR-MR22CW-J CPCR-MR55C CPCR-MR55C-H CPCR-MR55C-J CPCR-  
MR55C-M CPCR-MR55CW CPCR-MR55CW-H CPCR-MR55CW-J CPCR-MR55CW-M CPCR-MR75C  
CPCR-MR75C-H CPCR-MR99C CPCR-MR99C-M CPCR-QR756SC-2KCPCR-QR756SC-2KB