

cq??????????

1	8cq-2	15	2	0.025	220	2800	8	
2	10cq-3	15	3	0.025	220	2800	10	
3	14cq-5	20	5	0.12	220	2800	14	1
4	16cq-8	25	8	0.12	220/380	2800	16	1
5	20cq-12	50	12	0.37	220/380	2800	20	1
6	25cq-15	110	15	1.1	380	2800	25	2
7	32cq-15	110	15	1.1	380	2800	32	2
8	32cq-25	180	25	1.1	380	2800	32	2
9	40cq-20	180	20	2.2	380	2800	40	3
10	50cq-25	240	25	4.0	380	2800	50	4
11	50cq-32	240	32	4.0	380	2800	50	4
12	16cq-8	25	8	0.12	220/380	2800	16	1
13	20cq-12	50	12	0.37	220/380	2800	20	1
14	25cq-15	110	15	1.1	380	2800	25	2
15	32cq-15	110	15	1.1	380	2800	32	2
16	32cq-25	110	25	1.1	380	2800	32	2
17	40cq-20	180	20	2.2	380	2800	40	3
18	40cq-32	180	32	4.0	380	2800	40	3
19	50cq-25	240	25	4.0	380	2800	50	4
20	50cq-40	220	40	4.0	380	2800	50	4
21	50cq-50	220	50	5.5	380	2800	50	4
22	65cq-25	280	25	5.5	380	2800	65	5
23	65cq-35	450	35	7.5	380	2800	65	5
24	65cq-50	450	50	11	380	2800	65	5
25	80cq-32	850	32	11	380	2800	80	6
26	80cq-50	850	50	15	380	2800	80	6
27	100cq-32	1667	32	22	380	2800	100	8
28	100cq-50	1667	50	30	380	2800	100	8