

???? ?mm2?	???? ??/???mm?	???? ?mm?	???? ?mm?	20 ?????????? ??/km?	???? ?m?
------------	----------------	-----------	-----------	-------------------------	----------

0.014	7/0.05	0.15	0.45	1454
0.035	7/0.08	0.15	0.60	568
0.05	7/0.10	0.15	0.60	356
0.08	7/0.12	0.20	0.78	245
0.12	7/0.15	0.25	0.95	163
0.20	7/0.20	0.25	1.10	90.4
0.35	19/0.16	0.25	1.30	53.1
0.50	19/0.18	0.25	1.40	40.1

0.75	19/0.23	0.25	1.70	24.6
1.0	19/0.26	0.25	1.80	20.4
1.20	19/0.28	0.30	2.0	16.6
1.50	19/0.32	0.30	2.25	12.7
2.0	19/0.37	0.30	2.45	10.0
2.5	19/0.41	0.40	2.80	7.43
4.0	37/0.37	0.40	3.40	4.88
6.0	37/0.45	0.50	4.20	3.30
8.0	133/0.28	0.5	5.2	2.30
10	133/0.32	0.5	5.8	1.82

16	133/0.39	0.6	7.0	1.22
20	133/0.45	0.6	8.0	0.919
25	196/0.40	0.6	8.8	0.795
35	494/0.30	0.7	10.4	0.565
50	396/0.40	0.8	12.2	0.393
70	551/0.40	1.0	14.6	0.277
95	760/0.40	1.2	17.2	0.210
0.03	1/0.20	0.15	0.50	560
0.05	1/0.25	0.18	0.60	386.9
0.07	1/0.30	0.2	0.70	245

0.12	1/0.40	0.20	0.80	146.9
0.20	1/0.50	0.25	1.0	94
0.3	1/0.60	0.25	1.10	65.3
0.5	1/0.80	0.30	1.40	36.7
0.75	1/0.97	0.25	1.48	24.7
0.78	1/1.0	0.30	1.60	24.7
1	1/1.13	0.30	1.70	18.2
1.13	1/1.20	0.30	1.80	16.5
2.5	1/1.78	0.40	2.60	7.56

????????????????????????????