

# 3VL9300-3HF05

产品名称	3VL9300-3HF05
公司名称	厦门卡库电气有限公司
价格	99.00/个
规格参数	品牌:西门子 型号:3VL9300-3HF05
公司地址	厦门市湖里区安岭路966-968号汇金湖里大厦815号之一
联系电话	0592-5709823 18030229052

## 产品详情

3VL9300-3HF05

3VL9300-3HF05

精心，细心，用心，品质永保您称心‘ ’ 厦门卡库 品质第一，永远诚信经营！欢迎来电。

我们承诺【对于每一个询价我们都会用最真挚的态度处理】

我们承诺【对于客户每一个问题我们都会给您最满意的答复】

我们承诺【对于每一个订单我们都会进行一站到底的跟踪和服务】

厦门卡库电气有限公司

联系人：严小姐

手机：18030229052

电话：0592-5709823

传真：0592-5709828

QQ：1093230189

了解过CPU工作模式及优先级：高优先级有STOP、HOLDUP、STARTUP ( WARMRESTART、COLDRES

TART);低优先级有:RUN、RUN-P(PG/PC的在线读写程序)。查看CPU是在RUN模式,或是在STOP模式,又或是RUN模式的闪烁状态和STOP模式兼有的保持模式或叫调试模式。如果仅是RUN模式则CPU和各板为正常进行第3步。如果是保持模式出现,可能是运行过程中用户程序出现断点而处于调试程序状态,或在启动模式下断点出现,对此情况重新调试好程序,再次将控制程序下载到CPU中方可。如果是STOP模式,目测引起STOP的原因分析:A、无电,分析无电原因,是因为供电部门出问题,还是异常掉电(因有有1K3AH的UPS保证很少发生异常掉情况),通常情况下为检修拉电了,待检修结束后进行人工送电。再利用PLC的在线功能将CPU的工作模式从STOP转换为RUN;B、CPU坏,更换新的好的同种类型同版本的CPU;C、有板子坏了,有序进行板子的更换。对于硬件更换时要注意使用与原来的器件相同的产品同型号、同版本来进行,否则会造成实际的PLC配置与相应编程软件中硬件配置数据库中硬件配置不同而无法进行用户控制程序的正常循环执行。3、进行各个主板和扩展板上的通讯电缆检查和各模块各LED灯的检察,看是否有坏模块出现fault灯亮,若有则该模块不正常。对于数字量输出模块上各点其实与现实生活上的电灯开关是一样的功能且为常开点,所以在线检修该模块的任一点时,只要在没有接线时且该地址在控制程序不给输出信号时来检测其通不通就可以了,若通,则该点不正常,不通则正常;不正常时要进行硬件连接线的另选点重接工作;另外我们也可以用新模块进行更换后,对替换下来的模块的点进行测量通断状态,通,则该点坏,不通该点为好。对于数字量输入模块的点当于导通的线圈,为常闭状态,它可以在线或下线检测,用表检测若是坏点的话则是不通的状态,则换点重接线;好点则为通状态。只要对硬件接线重新换点重接后均要用相应编程软件对控制软件进行0X或1X地址替换工作。对于模拟量输入模块是与数字量输入模块相同,每个通道都相当于一根导线形式,也就是说相当于常闭点,所以检测通道好坏的方法为用表的测通断功能来检测,当通状态时为好,断状态时为坏通道;模拟量输出模块的检测方法与数字量输出模块相同。若坏通道则对硬件接线需要更换通道与并同时替换控制程序中的相应3X或4X地址;另外对于模拟量模块则要进行量程块的选择的检查,保险丝是否断开的检查等工作。软件配置是否正常,一般为电压1~5V或电流4~20mA,这根据所用的传感器与智能转换器类型来选择。进行过硬件点或通道更换工作后条件允许的话均要STOP PLC的CPU,再重新下载程序,若条件不允许则直接用更新变化来下载变化的程序而不停CPU。对于不用的输入模块的好通道/好点与最后一个已用的一好通道/好点进行串联或在软件中进行特别设置。

NEW TEXTRON ACCUDRIVE MSH057228S-3 25:1 WORM GEAR REDUCER D383536

NEW BALDOR ECP83663T-4 841XL 5HP 460V-AC 3505RPM 184T 3PH

NEW ITT CANNON FV-F3700106200 FABRI-VALVE 6 IN STEEL KNIFE GATE

BINGHAM 2-1/2 IN BORE 14-1/2 IN OD STAINLESS PUMP IMPELLER

NEW 10186611 BEARING COLUMN TEE ASSEMBLY STAINLESS D476722

ITI 3216 INKJET CONTROLLER MARKSMAN 6000 REV B 110V-AC D245754

NEW MOYNO 33260 3/4 IN NPT 208-230/460V-AC 1/2HP IRON CAVITY PUMP

DEZURIK 228-401671 KGSV STAINLESS 150 6 IN KNIFE GATE VALVE

NEW SPARKS DURA-DRIVE PLUS STAINLESS CONVEYOR DRIVE ROLLER 0.50HP

C2080H 2 IN 40FT SINGLE STRAND RIVETED ROLLER CHAIN B469465

NEW DOMINO L005200 DIGILASE CONTROLLER LASER CODER BOARD REV AF

PIRANHA PUMPS PP-100 DEWATERING 2 IN 115V-AC 1HP 90GPM

ROSEMOUNT 8800A F060SA1N1P1I5 SMART VORTEX STAINLESS 6IN 150 FLOW

NEW CLARK-RELIANCE W350X-C8-EA17 LEVALARM WATER COLUMN FUEL CUT

FISHER GS 667 SIZE 34 2 IN BRONZE PNEUMATIC THREADED CONTROL

ABB PS 130/6-90-P-PMB-3737 3 HAB 4040-1 ELMO ROBOTICS 90V-DC

ITT 5-201-06-060-004 TCF COMPLETE HEAT EXCHANGER 300/150PSI 2IN

ALLEN BRADLEY 1785-L40E PLC-5/40 ETHERNET CPU PROCESSOR MODULE

GE FANUC DS3800DGRC1B1C 6BA03 GENERATOR REGULATOR PCB CIRCUIT

NEW STACO PIG40MAG100-102 PIPE PIG SILICONE 4IN 12IN LENGTH

NEW DODGE 011157 PARA-FLEX PX160 4040 CLUTCH 5 IN STEEL FLANGE

REXROTH HNL02.1R-0980-C0023-A-480-NNNN 380-480V-AC 23A SERVO

MICRO MOTION DS150S141SC MASS FLOW SENSOR 1500PSI 1-1/2 IN FLOW

NEW SIEMENS 01-306-042-501 MOVEABLE CONTACT BLADE 138KV ANGLE

AHLSTROM? PUMP POWER END IMPELLER-10IN-OD 2VANE 1-1/2IN-SHAFT

NEW THERMO RAMSEY ECW950 100401 REV D PCB CIRCUIT BOARD D445973

BENTLY NEVADA 3500/42M M2 PROXIMITOR/SEISMIC MONITOR I/O MODULE

NEW HORNER HE693THM884M THERMOCOUPLE INPUT MODULE D507660

NEW BENTLY NEVADA 3500/42M M2 PROXIMITOR/SEISMIC MONITOR MODULE

NEW BENTLY NEVADA 3500/42M M2 PROXIMITOR/SEISMIC MONITOR I/O

GOULDS 3SL1F06E1 NPV IMMERSSED SUCTION 1-1/2 X 2 - 6 IN MULTI-

NEW GENERAL ELECTRIC GE THJK636F000 3P 600A AMP 600V-AC CIRCUIT

NEW TLV MC-GA2 100-240V-AC 75VA ELECTRIC STEEL ACTUATOR

NEW B/W CONTROLS 53-1203 INTRINSICALLY SAFE CONTROL 53 115/230V-

BENSHAW RS6-75-5-C SOLID STATE AC 75HP 575V-AC 60HZ 80A AMP MOTOR

ABB PS 130/6-90-P-PMB-3737 3 HAB 4040-1/5 ELMO ROBOTICS SERVO

GENERAL ELECTRIC GE DS3800HI0A1B1D INPUT ISOLATOR PCB CIRCUIT

GENERAL ELECTRIC GE 44B371588G01 DIAGNOSTIC READOUT PCB CIRCUIT

NEW ABB YXT 117 YT296000-SP BASIC FIELD CONTROL UNIT PCB CIRCUIT

NEW ABB DSMB 144 57360001-EL/1 MEMORY PCB CIRCUIT BOARD D495724

NEW SST 5136-SD-ISA DIRECT LINK INTERFACE CARD PCB CIRCUIT BOARD

OVATION 5X00241G01 PROCESSOR MODULE D507954

2100503-2 4 VANE 19-1/2 IN OD STAINLESS PUMP IMPELLER REPLACEMENT

NEW SCHNEIDER SM-100/50/030/P0/45/S1/B1 PACDRIVE SERVO MOTOR

DODGE 140CM21A 1750 RPM 13/16 IN 1-1/2 IN 2.75HP 50:1 WORM GEAR

NEW PARKER PTR252-1003F-AB23-C 250PSI PNEUMATIC ACTUATOR ASSEMBLY

NEW DUFF NORTON LDM10006-491B WORM GEAR ACTUATOR ASSEMBLY D456819

NEW BALDOR IDWNM3611T WASHDOWN INVERTER 3HP 230/460V-AC 184TC

FOXBORO 2801-SABA-TSA-L 1 IN TEFLON 120V-AC MAGNETIC FLOW METER

ARMSTRONG H51 1-1/2 IN 1/4HP 115V-AC CIRCULATOR PUMP B423919

ARMSTRONG 1B 1050-003 1-1/2 IN 1/4HP 115V-AC CIRCULATOR PUMP

HOFFMAN UU756040 758MM FIBERGLASS 595MM 421MM WALL-MOUNT

NEW INTECOLOR E01940-20E 19 IN ASSEMBLY COLOR DISPLAY CRT MONITOR

NEW NORD 100 L/4OUS 12080AZD-100 L/4CUS 3HP 230/460V 7.55:1 GEAR

GEAR 5.1-41RPM MOTOR D426823

NEW AMD 53-000264 386-SI PCB CPU PROCESSOR D477981

NEW GE DE33ED4 TED134030 FLEX-A-PLUG BUS-WAY 480V 30A BREAKER MCC

NEW ELECTRO MECHANICAL 37805 TEST EQUIPMENT MODULE ASSEMBLY

IRT SA 1310-RACK SERVO CONTROLLER B433119

NEW VIDEOJET 600552 PRINTER PCB CIRCUIT BOARD D503954

MEASUREX 05371800 08564302 BUFFERED SERIAL CONTROL F PCB CIRCUIT

ALLEN BRADLEY 1336S-C007-AA-DE 7-1/2HP 0-575V-AC 0-400HZ 10A

NEW HI-SPEED 5D-01B-0012 P2-08-130 CONTROL PCB CIRCUIT BOARD REV

HONEYWELL 82408667-001 CB535 ROM RAM MEMORY CARD BOARD D368034

NEW CATERPILLAR CAT 197-8662 STEERING ACCUMULATOR BLADDER

ABB DS3800DGRC1C1D 6BA05 GENERATOR REGULATOR PCB CIRCUIT BOARD

NEW WITTENSTEIN ALPHA VDT 050-MF1-10-031-AC V-DRIVE 10:1 WORM

NEW CONE DRIVE H035-4 TEXTRON 1-3/16 IN 1-7/8 IN 30:1 WORM GEAR

NEW EMERSON 3120-426 3HP 180V-DC 1750RPM 184C DC ELECTRIC MOTOR