

??AlMn10	??CuNi15	?????HT-LJ3
??AlMn20	??CuFe10	?????HT-LJ4
??AlTi5	??CuSb50	?????HT-LJ5
??AlTi10	??CuBe4	?????HT-LJ6
??AlNi10	??CuP15	???HT-LQ
??AlCr5	??CuMg20	?????HT-LDQ
??AlCr10	???CuRe20	?????HT-LWQ
??AlCr20	??CuTi30	???HT-LF
??AlZr5	??CuZr40	?????HT-LWF
??AlSb4	??CuB5	???HT-LB
??AlSb10	???????	?????HT-LLB
??AlFe20	???????	???????HT-LSB
??AlBe1	???????	???HT-LCM
??AlBe3	???????	???HT-LCN
??AlBe5	???B18Ni	???HT-LCG
??AlB3	???????	???HT-LQL
???(?/?)AlTi5B1	???HT-Ti4OB4	???HT-LR
???AlRe10	??HT-Ti75	???????
?????AlTi5B1Re10	?? HT-Mn75	??????????DFCT-1
???AlTi5C0.2	?? HT-Cu75	????????DFCT-2
??AlSr10	?? HT-Fe75	????????DFCT-4
??AlY5	?? HT-Cr75	???????
??AlBi10	?? HT-Ni75	????HT-MJ
	?? HT-Zn75	????HT-MF
	???HT-Si95	??? ???DFCT-6