



RPI-222 ROHM DIP

RLZTE-1127B ROHM LL34-27V

RF2001T3D ROHM TO-220

BD4726G-TR ROHM SOT23-5

SP8M8-FD5-TB ROHM SOP8

BH1417FV-E2 ROHM SOP

DA204UT106 ROHM SOT23

PTZTE2524B ROHM 1W-24V

2SA1037AKT146Q-K ROHM SOT23

MTZJT-776.8B-M ROHM MSD(DO-34)

SML521MUWT86 ROHM SOT23

DTA124EKAT146 ROHM SOT23

MTZJT-779.1C-M ROHM SOT23

UDZSTE17 11B ROHM SOD323

2SB1326TV2R ROHM SOP

SP8K1-TB ROHM SOP-8

BD6709JFS-E2 ROHM SOP

BD6669FV-E2 ROHM TSSOP

RLZTE-1111B ROHM LL34

FW360-TL-E ROHM SOP

BA3308 ROHM SIP

SLA-370LT3F-M ROHM SOP

2SD2142KT146 ROHM SOT-23

UDZSTE-1716B ROHM SOP

TC74VHCU04FT(EL) TOSHIBA SOP

2SD2537T100V ROHM SOT89

SP8M24-TB ROHM SOP8

?????????????????? ??? ??137 2863 5748 ???????www.cr-ic.com???