

Waddington控制器PSENC10010

| | |
|------|--------------------------|
| 产品名称 | Waddington控制器PSENC10010 |
| 公司名称 | 上海航欧机电设备有限公司 |
| 价格 | 1200.00/台 |
| 规格参数 | |
| 公司地址 | 上海市普陀区中江路388弄1号楼905室 |
| 联系电话 | 021-51085161 13045641319 |

产品详情

Waddington电源，Waddington控制器，Waddington动力控制

Waddington工厂商

上海航欧Waddington电源，Waddington控制器，Waddington动力控制，上海航欧机电设备有限公司专业从事进口机电设备、仪器仪表等疑难备品备件的销售，是经营世界各地进口设备机电配件的现代化企业。

上海航欧公司与众多知名品牌电子元件供应商建立有极其良好的合作关系，在欧美、日本等地形成了稳定、的供应网络，专业的询价渠道和多年的行业经验，更使我们在价格及货期上有很大优势。

经销产品供应的行业涉及冶金、钢铁、石化、能源、航天、集装箱码头、汽车、水利、造纸、电厂、纺织、注塑、橡胶、医疗、食品包装等。

我们热忱地希望尽我们的努力，力争优惠的产品价格，供货周期以及服务质量，能够为您解决进口备件方面的问题。

优势进口产品主要有：传感器，测速电机，接近开关，电子尺，编码器，控制器、分析仪，光纤，光栅，插装阀，电缆，拖链，分配器，马达，减速机，继电器、缓冲器和进口五金

Waddington Electric was founded in 1956 by my grandfather. The company did machine and industrial wiring.

Prior to this, he was an employee of Brown and Sharp, and had completed a full apprenticeship program there.

My father ran the company from about 1962, when my grandfather decided to retire to Florida.

We changed the name to Waddington Electronics in the 80s to better reflect the times. The bulk of our business

concentrated on supplying custom CNC machine control panels to many of the machine tool builders in the southern New England area.

We built our first roll feeds in 1984, outsourcing all of the machining.

主要型号：PSPCB10000

PSPCB10000-BIN

PSENC10000

PSENC10031

PSENC10032

PSENC10009

PSENC10010

PSENC10000-NE

PSENC10001

PSENC10021

PSENC10035

PSENC50002

PCDIO10003

PCDIO10008

PCDIO10000

STTOPLIMIT1

STTOPLIMIT2

STBOTTOMLIMIT1

STBOTTOMLIMIT2

ST2NDTOPLIMIT

ST2NDBOTTOMLIMI

PSCBL70012

PSCBL70006

PSCBL70008

PSCBL70013

PSCBL70014

PSCBL70019

PSCBL70015

WESTAMRSH2R1

WESTAMRSH2R2

WESTAMRSH2R2SST

WESTAMRSH3

WESTAMRSH2R1H

WESTAMRSH2R2H

WESTAMRSH2FG

WESTAMRSH2R2HFG

WESTASSH1

WESTASSH2

STHEAD sonatrol head options Extra sensors

WESTAMRSH2R1 mrsh-2/r1 5in-20ft sonarsensor 3800

WESTAMRSH2R2 mrsh-2/r2 18in-20ft sonarsenso 3800

WESTAMRSH2R2SST mrsh-2/r2 18in-20ft ss transdu 5500

WESTAMRSH3 sonatrol sensor with dual 7700

WESTAMRSH2R1H r1sensor w/ horn N 8800

WESTAMRSH2R2H r2sensor w/ horn N 8800

WESTAMRSH2FG mrsh-2fg sensor r2 fixed gain 0000

WESTAMRSH2R2HFG r2sensor w/ horn andfixed gain N 2000

WESTASSSH1 r-1 stainless steel sensor 7500

WESTASSSH2 r-2 stainless steel sensor 7500

STWESTA30FT st6z mods for 30 ft range Range Mods

WESTA30FT st6z mods for 30 ft range 000

STWESTAAOAB air output a/b option

WESTAAOAB air output a / b selec switch \$ -

STWESTAAUTO/MAN auto manual out put option

WESTAAUTO/MAN auto/manual selector switch \$ -

STWESTAF/V1 freq to voltage option

WEEZAFV1 f/v-1 frequency to voltage oe Y \$ -

STWESTAGUIDE001 sensor guide adjust able width call

WESTASTANDWH1 stand-wh sensor stand w/wheels N 3000

STWESTAMTRSEL dc motor sel a/b contactor

WESTAMTRSEL dc motor sel a/b contactor 5000

STWESTAUTF1 upper time filter option

WESTAUTF1 utf-1 upper time filter option \$ -

STWEST/F1 voltage to frequecny option

PSMDL04 v/f-1 voltage to frequency \$ -

WESTAQCON Sensor Head quick connector \$ -

STWESTAMUX2 option analog multiplier

WESTAMUX2 mux-2 analog multiplier option 8900

STWESTAHVAO1 option 0-90v dc output

WESTAHVAO1 hvao-1 0-90vdc output option 2500

STWESTAJOG option jog option

WESTAJOG jog pushbutton option \$ -

STWESTALFO1 option ac line filter

WESTALFO1 lfo-1 ac line filter option 500

STWESTATAP1 option percent taper option

WESTATAP1 tap-1 percent taper option 1800

STWESTATW1 option limit thumbwheel setpoi

WESTATW1 thumbwheel set point pot 5000

STWESTARP1 option remote distance pot

WESTARP1 rp-1 10 turn remote distance 000

STWESTARP2 option remote gain pot

WESTARP2 rp-2 ten turn remote gain 000

STWESTARP3 option remote speed on output

WESTARP3 option remote speed on output 000

STWESTAPT1 option payoff/takeup switch

WESTAPT1 payout take up switch option 500

STWESTAFR1 option forward reverse switch

WESTAFR1 fr-1 forward-reverse switch 500

STWESTAMAO20 option 4-20 ma output current loop optput

WESTAMAO20 mao-20 4-20ma output option 6600

STWESTAMAO10 option 0-10 ma output

WESTAMAO10 mao-10 0-10ma output option 6600

STWESTABOB1 option 12 bit binary output 12 bit binary output

WESTABOB1 bob-1 12bit binary output 5000

STWESTASY2M option sy2 sequencer(master op Sequencer for 2 units operating close together

WESTASY2M sy2-m sy-2 sequencer master 5000 master

STWESTASYS option sle option

WESTASYS sy-s sle option 000 sle

STWESTASY8 option sy8 sequencer

WESTASY8 sy-8 8 unit sequencing option 6000 8 CH sequencer for up to 8 units close together

STWESTASTAND1 option sensorhead stand

WESTASTAND1A stand-1 sensor head stand N 0900 Sensor Stands

WESTASTAND10 stand with spool guide N \$ -

WESTASTAND1B sensor head stand with guides N \$ -

STWESTASTANDWH1 stand-wh sensor stand w/wheels

WESTASTANDWH1 stand-wh sensor stand w/wheels N 8200

STWESTARAAC1 cable adapter rapid air raac1 Adapter Cables for other OEM equipment

WESTARAAC1 raac-1 5 pin rapid adapter 000

STWESTARAAC2 option 15 pin rapidair cable

WESTARAAC2 raac-2 V2 rapid air adapter 500

STWESTARAAC2J option 15 pin rapidair cable

WESTARAAC2J raac-2j rapid air adapter 0000

STWESTAGOODMAN1 option cable to goodman cutter

WESTAGOODMAN1 goodman cutter adapter 15 ft 000

STWESTARAAC3 option d shell rapidair connec

WESTARAAC3 rapid air d-shell adapter 500

STWESTADIV2 option analog divider

WESTADIV2 div-2 analog divider option 0000

STWESTABSO1 option base speed option

WESTABSO1 bso-1 base speed option 7500

STWESTAAOM1 option analog meter output meters

WESTAAOM2 analog meter 0-90 vdc \$ -

WESTAAOM1 aom-1 analog output meter+-15 0000

STWESTADMS1 option digital display

WESTADMS1 dms-1 digital display 9900

STWESTAEAO1 option extra analog output Extra analog outputs

WESTAEAO1 eoa-1 normal extra analog 5000

STWESTAEAON1 option extra analog output inv

WESTAEAON1 eaon-1 inverted extra analog 5000

STWESTADUAL option relay for dual sensor o

WESTADUAL relay option for dual heads 6500 Relay for 2nd sensor switchable

STWESTATOGGLE option on off toggle switch

WESTATOGGLE on/off toggle switch option 500 on off power switch

STWESTASUM3 option line speed summing

WESTASUM3 sum-3 3input summing amplifier 7600 Summing input

STWESTATC6 option tension control(auto/ma

WESTATC6 tc-6 tension control option 0000

STWESTADF1 option dust filter option Dust filter for sensor

WESTADF1 df-1 dust filter for 500

STWESTAPID2 option pid output

WESTAPID2 pid2 output option 6500 PID Output

STWESTAONOFF two setpoint on off control

WESTAONOFF 2-set point on/off relay 500 dual setpoint On/Off relay

WEPTAONOFFNS

WEPTAPT1LSA

WEPTAPT1-1

PTTOPLIMIT

WEPTATL1

PTBOTTOMLIMIT

WEPTABL1

PTSTAND

WEPTASTAND

PTWESTAEXTBASE

WESTAEXTBASE

STWESTAMAO20

WESTAMAO20

STWESTAMAO10

WESTAMAO10

STWESTARAAC1

WESTARAAC1

STWESTARAAC2

WESTARAAC2

STWESTARAAC2J

WESTARAAC2J

STWESTARAAC3

WESTARAAC3

STWESTASUM3

WESTASUM3

PSOSDA10003

PSENC10032-PT

PSDRV10001-PT

PSDRV10002-PT

PSSPR10000

PSPTA10006

PSOPR10001

STWESTAF/V1

WEEZAFV1

STWESTAAOM1

WESTAAOM2

