

雨水混流泵维修 金石泵业 江西雨水混流泵

产品名称	雨水混流泵维修 金石泵业 江西雨水混流泵
公司名称	泰安金石泵业有限公司
价格	面议
规格参数	
公司地址	山东省泰安市泰山区南关路12号
联系电话	13605386905

产品详情

混流泵

潜水电泵

磁悬浮潜水电泵它实现了世界潜水电泵领域重大突破，有效解决了传统潜水电泵的种种弊端：如转换效率偏低、耗电过高、扬程受限、轴承易损、检修频繁等。广泛应用于工矿企业的供排水、农田灌溉及高原、山区供水等领域。

磁悬浮潜水电泵它以独有的专利技术改变了潜水电泵的制造工艺，雨水混流泵维修，转换效率达到令人的新水平，创造了巨大节能降耗效益。

磁悬浮潜水电泵解决了制约世界潜水电泵领域发展的轴向力问题，潜水电泵的扬程有了突破性提高，雨水混流泵采购价，填补了超高扬程(单机扬程设计到上千米)和超大流量(高承载)潜水电泵的市场空白；扬程、流量曲线趋于平缓。其转换效率、单机扬程均居世界地位。

混流泵

水工及其它方面

机组进水流道设计不合理或与机组不配套、水泵淹没深度不当，雨水混流泵安装，以及机组启动和停机顺序不合理等，都会使进水条件恶化，产生漩涡，诱发汽蚀或加重机组及泵房振动。采用破坏虹吸真空断流的机组在启动时，若驼峰段空气挟带困难，形成虹吸时间过长；拍门断流的机组拍门设计不合理，时开时闭，不断撞击拍门座；支撑水泵和电机的基础发生不均匀沉陷或基础的刚性较差等原因，也都会导致机组发生振动。

使用与保养：Use And

Maintenance

1、经常检查轴承温度，轴承箱内应装70%的钙基黄油，不得过多或过少，轴承升温一般不得比周围超过35 ° C，轴承的极限温度不得超过75 ° C（用手摸感到烫手），若超过应停车检查原因予以消除。

Check the bearing temperature

regularly. The bearing box should be put 70% butter，江西雨水混流泵，it can not be too much or

too little. The temperature rising of bearing can not be more than 35 ° C higher

than around temperature and the limiting temperature of bearing is 75 ° C，if the temperature is higher than 75 ° C，stop to check the reason and adjust it.

雨水混流泵维修-金石泵业(在线咨询)-江西雨水混流泵由泰安金石泵业有限公司提供。泰安金石泵业有限公司（www.tajsby.cn）为客户提供“水泵,泥浆泵,混流泵,轴流泵,渣浆泵”等业务，公司拥有“金石泵业”等品牌，专注于污水泵、杂质泵等行业。欢迎来电垂询，联系人：刘经理。